

**Historic Resources Inventory
Buildings and Structures**

**State of Connecticut
State Historic Preservation Office
59 South Prospect Street, Hartford, CT 06106
203-566-3005**

FOR OFFICE USE ONLY	
Town No.	Site No.
UTM	
QUAD	
District <input type="checkbox"/> S <input type="checkbox"/> NR	If NR Specify <input type="checkbox"/> Actual <input type="checkbox"/> Potential

IDENTIFICATION NUMBER	1. Building Name (Common)		(Historic)		
	2. Town/City <u>Westport</u>		Village	County <u>Fairfield</u>	
	3. Street and Number (and /or location) <u>8 Mayflower Parkway</u>				
	4. Owner(s) <u>Dolores M. Jackson</u>		<input type="checkbox"/> Public		<input checked="" type="checkbox"/> Private
	5. Use (Present) <u>Residential</u>		(Historic)		
	6. Accessibility To Public:	Exterior Visible from Public Road <input checked="" type="radio"/> Yes <input type="radio"/> No	Interior Accessible <input type="radio"/> Yes <input checked="" type="radio"/> No	If yes, explain	
	7. Style of Building <u>Colonial Revival</u>		Date of Construction <u>1926</u>		
	8. Material(s) (Indicate use or location when appropriate)				
	<input type="checkbox"/> Clapboard <input type="checkbox"/> Asbestos siding <input type="checkbox"/> Brick <input type="checkbox"/> Other <input checked="" type="checkbox"/> Wood shingle <input type="checkbox"/> Asphalt siding <input type="checkbox"/> Fieldstone (Specify) _____ <input type="checkbox"/> Board & batten <input type="checkbox"/> Stucco <input type="checkbox"/> Cobblestone <input type="checkbox"/> Aluminum Siding <input type="checkbox"/> Concrete Type: _____ <input type="checkbox"/> Cut stone Type: _____				
	9. Structural System				
	<input checked="" type="checkbox"/> Wood frame <input type="checkbox"/> Post and beam <input type="checkbox"/> Balloon <input type="checkbox"/> Load-bearing masonry <input type="checkbox"/> Structural iron or steel <input type="checkbox"/> Other (Specify) _____				
	10. Roof (Type)				
	<input checked="" type="checkbox"/> Gable <input type="checkbox"/> Flat <input type="checkbox"/> Mansard <input type="checkbox"/> Monitor <input type="checkbox"/> Sawtooth <input type="checkbox"/> Gambrel <input type="checkbox"/> Shed <input type="checkbox"/> Hip <input type="checkbox"/> Round <input type="checkbox"/> Other (Specify) _____ Material <input type="checkbox"/> Wood shingle <input type="checkbox"/> Roll asphalt <input type="checkbox"/> Tin <input type="checkbox"/> Slate <input type="checkbox"/> Other (Specify) _____ <input checked="" type="checkbox"/> Asphalt shingle <input type="checkbox"/> Built up <input type="checkbox"/> Tile				
	11. Number of Stories <u>2</u>		Approximate Dimensions <u>76' X 30'</u>		
	12. Condition (Structural)		Exterior		
	<input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated		<input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated		
13. Integrity (Location)		When?	Alterations	If yes, explain	
<input checked="" type="checkbox"/> On original site <input type="checkbox"/> Moved			<input type="radio"/> Yes <input checked="" type="radio"/> No		
14. Related Outbuildings or landscape features					
<input type="checkbox"/> Barn <input type="checkbox"/> Shed <input type="checkbox"/> Garage <input type="checkbox"/> Other Landscape features or buildings (specify) <input type="checkbox"/> Carriage House <input type="checkbox"/> Shop <input type="checkbox"/> Garden					
15. Surrounding Environment					
<input type="checkbox"/> Open Land <input type="checkbox"/> Woodland <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Scattered buildings visible from site <input type="checkbox"/> Commercial <input type="checkbox"/> Industrial <input type="checkbox"/> Rural <input type="checkbox"/> High building density					
16. Interrelationship of building and surroundings <u>Suburban Residential Neighborhood</u>					

DESCRIPTION

17. Other Notable features of building or site (interior and/or exterior)

18. Architect Builder

SIGNIFICANCE

19. Historical or Architectural Importance

SOURCES

PHOTO	Photographer Phillip Esser	Date April 2008	Place Photograph Here
PHOTO	View Southwest; south	Negative on File	
COMPILE	Name Phillip Esser & Paul Graziano	Date June 2008	
RELEASE	Organization Associated Cultural Resource Consultants		
BY	Address 54 Danbury Road, Suite 227, Ridgefield, CT 06877		

20. Subsequent Field Evaluations

21. Threats to building or site

None Known
 Highways
 Vandalism
 Developers
 Other _____

Renewal
 Private
 Deterioration
 Zoning
 Explanation _____

STATE OF CONNECTICUT
COMMISSION ON CULTURE AND TOURISM
One Constitution Plaza, Hartford CT 06103

HISTORIC RESOURCES INVENTORY FORM
For Buildings and Structures

CONTINUATION SHEET

Consultant's Name: ACRC

Property Address: 8 Mayflower Parkway, Westport, CT

FOR OFFICE USE ONLY		
TOWN NO:	SITE NO:	UTM:
18/___/___/___/___/___		
QUAD:		
DISTRICT:	NR:	Actual Potential



**Historic Resources Inventory
Buildings and Structures**

**State of Connecticut
State Historic Preservation Office
59 South Prospect Street, Hartford, CT 06106
203-566-3005**

FOR OFFICE USE ONLY	
Town No.	Site No.
UTM	
QUAD	
District <input type="checkbox"/> S <input type="checkbox"/> NR	If NR Specify <input type="checkbox"/> Actual <input type="checkbox"/> Potential

I D E	1. Building Name (Common)		(Historic)
N T I	2. Town/City <u>Westport</u>	Village	County <u>Fairfield</u>
F I C	3. Street and Number (and /or location) <u>119 Compo Road South</u>		
A T	4. Owner(s) <u>Christine Mennie</u>		<input type="checkbox"/> Public <input checked="" type="checkbox"/> Private
I O	5. Use (Present) <u>Residential</u>		(Historic)
N	6. Accessibility To Public:	Exterior Visible from Public Road <input checked="" type="radio"/> Yes <input type="radio"/> No	Interior Accessible <input type="radio"/> Yes <input checked="" type="radio"/> No If yes, explain
D E S C R I P T I O N	7. Style of Building <u>Vernacular</u>		Date of Construction <u>ca. 1890</u>
8. Material(s) (Indicate use or location when appropriate)			
<input checked="" type="checkbox"/> Clapboard <input type="checkbox"/> Asbestos siding <input type="checkbox"/> Brick <input type="checkbox"/> Other <input type="checkbox"/> Wood shingle <input type="checkbox"/> Asphalt siding <input type="checkbox"/> Fieldstone (Specify) _____ <input type="checkbox"/> Board & batten <input type="checkbox"/> Stucco <input type="checkbox"/> Cobblestone <input type="checkbox"/> Aluminum Siding <input type="checkbox"/> Concrete <input type="checkbox"/> Cut stone Type: _____ Type: _____			
9. Structural System			
<input checked="" type="checkbox"/> Wood frame <input type="checkbox"/> Post and beam <input type="checkbox"/> Balloon <input type="checkbox"/> Load-bearing masonry <input type="checkbox"/> Structural iron or steel <input type="checkbox"/> Other (Specify) _____			
10. Roof (Type)			
<input checked="" type="checkbox"/> Gable <input type="checkbox"/> Flat <input type="checkbox"/> Mansard <input type="checkbox"/> Monitor <input type="checkbox"/> Sawtooth <input type="checkbox"/> Gambrel <input type="checkbox"/> Shed <input type="checkbox"/> Hip <input type="checkbox"/> Round <input type="checkbox"/> Other Material (Specify) _____ <input type="checkbox"/> Wood shingle <input type="checkbox"/> Roll asphalt <input type="checkbox"/> Tin <input type="checkbox"/> Slate <input type="checkbox"/> Other <input checked="" type="checkbox"/> Asphalt shingle <input type="checkbox"/> Built up <input type="checkbox"/> Tile (Specify) _____			
11. Number of Stories <u>2</u>		Approximate Dimensions <u>30' X 34'</u>	
12. Condition (Structural)			Exterior
<input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated			<input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated
13. Integrity (Location)		When?	Alterations
<input checked="" type="checkbox"/> On original site <input type="checkbox"/> Moved			<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, explain
14. Related Outbuildings or landscape features			
<input type="checkbox"/> Barn <input type="checkbox"/> Shed <input checked="" type="checkbox"/> Garage <input type="checkbox"/> Other Landscape features or buildings (specify) <input type="checkbox"/> Carriage House <input type="checkbox"/> Shop <input type="checkbox"/> Garden			
15. Surrounding Environment			
<input type="checkbox"/> Open Land <input type="checkbox"/> Woodland <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Scattered buildings visible from site <input type="checkbox"/> Commercial <input type="checkbox"/> Industrial <input type="checkbox"/> Rural <input type="checkbox"/> High building density			
16. Interrelationship of building and surroundings <u>Suburban Residential Neighborhood</u>			

D
E
S
C
R
I
P
T
I
O
N

17. Other Notable features of building or site (interior and/or exterior)

18. Architect

Builder

S
I
G
N
I
F
I
C
A
N
C
E

19. Historical or Architectural Importance

S
O
U
R
C
E
S

P H O T O	Photographer Phillip Esser	Date April 2008	Place Photograph Here
	View South; east	Negative on File	
C O M P I L E D	Name Phillip Esser & Paul Graziano	Date May 2008	
	Organization Associated Cultural Resource Consultants		
	Address 54 Danbury Road, Suite 227, Ridgefield, CT 06877		

20. Subsequent Field Evaluations

21. Threats to building or site

None Known
 Highways
 Vandalism
 Developers
 Other _____
 Renewal
 Private
 Deterioration
 Zoning
 Explanation _____

STATE OF CONNECTICUT
COMMISSION ON CULTURE AND TOURISM
One Constitution Plaza, Hartford CT 06103

HISTORIC RESOURCES INVENTORY FORM
For Buildings and Structures

CONTINUATION SHEET

Consultant's Name: ACRC

Property Address: 119 Compo Road South, Westport, CT

FOR OFFICE USE ONLY		
TOWN NO:	SITE NO:	UTM:
18/____/____/____/____/____		
QUAD:		
DISTRICT:	NR:	Actual Potential



STATE OF CONNECTICUT

CONNECTICUT HISTORICAL COMMISSION
59 South Prospect Street, Hartford, CT 06106

HISTORIC RESOURCES INVENTORY FORM
For Buildings and Structures

CONTINUATION SHEET

Item number: _____

PAL, Pawtucket, RI 02860
June 2000

Address: 40 Richmondville Avenue

Name: Lees Mfg. Co. Worker's House

NR District:

Local District:

Neg No.: 7:33

HRS ID No.: 0764

