



HISTORIC RESOURCES INVENTORY - BUILDING AND STRUCTURES

Please send completed form to: Stacey Vairo, National Register and State Register Coordinator,
Connecticut Commission on Culture & Tourism, One Constitution Plaza, 2nd Floor, Hartford, CT 06103

* Note: Please attach any additional or expanded information on a separate sheet.

GENERAL INFORMATION

Building Name (Common) _____
 Building Name (Historic) Jesup/Godillot House
 Street Address or Location 60 Jesup Road
 Town/City Westport Village _____ County Fairfield
 Owner(s) Smith Richardson Foundation Public Private

PROPERTY INFORMATION

Present Use: Civic
 Historic Use: Residential
 Accessibility to public: Exterior visible from public road? Yes No
 Interior accessible? Yes No If yes, explain _____
 Style of building Queen Anne (remodeled 1882) Date of Construction 1804

Material(s) (Indicate use or location when appropriate):

- | | | | | |
|--|--|--------------------------------------|--|--|
| <input checked="" type="checkbox"/> Clapboard | <input type="checkbox"/> Asbestos Siding | <input type="checkbox"/> Brick | <input checked="" type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding |
| <input type="checkbox"/> Fieldstone | <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Stucco | <input type="checkbox"/> Cobblestone | <input type="checkbox"/> Aluminum Siding |
| <input type="checkbox"/> Concrete (Type _____) | <input checked="" type="checkbox"/> Cut Stone (Type <u>Granite</u>) | <input type="checkbox"/> Other _____ | | |

Structural System

- Wood Frame Post & Beam Balloon Load bearing masonry Structural iron or steel
 Other _____

Roof (Type)

- Gable Flat Mansard Monitor Sawtooth
 Gambrel Shed Hip Round Other _____

(Material)

- Wood Shingle Roll Asphalt Tin Slate Asphalt Shingle
 Built up Tile Other _____

Number of Stories: 2.5 Approximate Dimensions _____

Structural Condition: Excellent Good Fair Deteriorated

Exterior Condition: Excellent Good Fair Deteriorated

Location Integrity: On original site Moved When? _____

Alterations? Yes No If yes, explain: _____

FOR OFFICE USE: Town # _____ Site # _____ UTM _____

District: S NR If NR, Specify: Actual Potential

PROPERTY INFORMATION (CONT'D)

Related outbuildings or landscape features:

- Barn Shed Garage Carriage House Shop Garden
- Other landscape features or buildings: Servant's quarters

Surrounding Environment:

- Open land Woodland Residential Commercial Industrial Rural
- High building density Scattered buildings visible from site

• Interrelationship of building and surroundings:

See Continuation Sheet

• Other notable features of building or site (*Interior and/or Exterior*)

See Continuation Sheet

Architect _____ Builder _____

• Historical or Architectural importance:

See Continuation Sheet

• Sources:

See Continuation Sheet

Photographer PAL _____ Date _____

View _____ Negative on File _____

Name _____ Date 12/13/2011

Organization PAL _____

Address 210 Lonsdale Avenue, Pawtucket, RI 02860

• Subsequent field evaluations:

Threats to the building or site:

- None known Highways Vandalism Developers Renewal Private
- Deterioration Zoning Other _____ Explanation _____

STATE OF CONNECTICUT

**COMMISSION ON CULTURE & TOURISM
STATE HISTORIC PRESERVATION OFFICE**

One Constitution Plaza, Second Floor, Hartford, CT 06103

HISTORIC RESOURCE INVENTORY FORM

For Buildings and Structures

CONTINUATION SHEET

Item Number: _____ Date: October 2011

PAL, Pawtucket, RI 02860

60 Jesup Road, Westport, CT

FOR OFFICE USE ONLY

TOWN NO.: _____ SITE NO.: _____

UTM: 18/____/____/____/____/____

QUAD: _____

DISTRICT: _____

NR: Actual

Potential

Interrelationship of building and surroundings:

The building is located on a small rise on the southwest side of Jesup Road. It is set close to the road and faces north. A grassy lawn slopes away from the south side of the building, and large shrubs planted in mulch beds border the foundation. Several deciduous trees dot the property. A gravel parking area lies directly to the east of the house. A large municipal parking lot is located to the south of the lot.

Other notable features of building or site (*Interior and/or Exterior*):

The building is a two-and-one-half-story, six-bay-by-five-bay, former single family resident originally constructed in the Federal style. The house was remodeled in the Queen Anne style in 1882. The wood shingle-clad, hip roof has lower cross gables on the north (facade) and west elevations and multiple gable-, hip-, and shed-roof dormers throughout. Three tall, corbelled chimneys rise from the north and south roof slopes. A wide cornice supported by scroll brackets runs along the eave. Each gable has wide, scroll sawn vergeboard with a decorative truss and brackets. The walls are clad in clapboard on the first story and scalloped wood shingles on the second story, gables, and dormers and rest on a brick foundation. Flat wood trim bands run between the first and second stories and along the top and bottom of the windows on the second story. A large, two-story wing is attached to the east elevation. It has a wood shingle-clad, hip roof with hip-roof dormers and wall finishes that match the main block of the house. A two-story bay window with a copper-clad roof, wood-shingle siding, and corner brackets projects out from beneath the gable on the facade. A one-story porch extends across the facade, west, and part of the south elevations. It has a hip roof supported by turned posts with a molded cornice, brackets, and railings with turned spindles. A portion of the porch extends out from the center of the facade and has a hip roof with a gable on the east, north, and west elevations that contain turned spindles and brackets. Another gable projects out on the west elevation of the porch with vergeboard and decorative trusses similar to the main roof gables. A porch with a hip roof, bracketed posts, and turned spindles is partially recessed into the south elevation of the east wing. A balcony supported by brackets is located in the attic-story between two gables on the south elevation of the main block of the building. The original primary entrance is located in north end of the east elevation and consists of a pair of wood panel doors with arched windows in the top half. A secondary entrance is located in the east elevation of the bay window on the facade. Windows consists primarily of singles and pairs of two-over-two, double-hung sash in varying sizes with wide wood trim. The pairs of windows in the gables on the facade and west elevations have heavy lintels with denticulated cornices and brackets. An oval, fixed sash window with molded trim is located in the east end of the north elevation of the wing. There are minimal alterations to the building, which include the replacement of some exterior cladding and windows with one-over-one, double-hung sash.

Historical or Architectural importance:

The original building on this lot was constructed in 1804 by Dr. Ebenezer Jesup for his daughter, Abigail. Abigail married Eliphalet Swift in 1806, and the couple remained in the house until the late 1850s. The house changed hands several times over the 1860s and 1870s until it was purchased by Alexis and Julia Godillot Jr. Godillot in 1879. Godillot, who owned a French import business, greatly expanded and elaborated the house and grounds and constructed several outbuildings in 1882. In 1901, the property was transferred to the Godillot's son, lawyer John F. Godillot. In 1920, the lot was sold to Elizabeth Lyman, a nurse at the Westport Sanatorium, who converted the building into a boarding house. By 1946, the house had been converted to apartments. In 1951, the property was purchased by the Town of Westport and renovated to serve as offices for the Board of Education. The 1960 directory indicates that the address contained the Department of Public Welfare, the Health Department, the Civil Defense Department, and the Engineering Department. These offices remained at the address through the late 1970s. In 1980, the lot was listed as vacant; and by 1985 the building contained seven offices, including three real estate agencies, an architect's studio, and a business called Westport Navigation Inc.

STATE OF CONNECTICUT

**COMMISSION ON CULTURE & TOURISM
STATE HISTORIC PRESERVATION OFFICE**

One Constitution Plaza, Second Floor, Hartford, CT 06103

HISTORIC RESOURCE INVENTORY FORM

For Buildings and Structures

CONTINUATION SHEET

Item Number: _____ Date: October 2011

Six years later, the listing for the address included a securities company, a management corporation, a capital management firm, and several personal offices. Currently, the building is owned by Smith Richardson Foundation and holds The Levitt Pavilion for Performing Arts' venue space.

Sources:

Brown, T. Robins. Godillot Place NR. Hartford: CT Historical Commission, 1977; Westport Directory (W.D.).
Loveland, CO: US West Marketing Resources, 1991; W.D. Chicago, IL: Johnson Publishing Co., 1985; W.D.
Providence, RI: C. DeWitt White Co., 1917-1918; W.D. New Haven: The Price & Lee Co., 1923-1974; Westport
Assessor's Online Database, 2011.

FOR OFFICE USE ONLY

TOWN NO.: _____ SITE NO.: _____

UTM: 18/____/____/____/____/____

QUAD: _____

DISTRICT: _____

NR: Actual

Potential

STATE OF CONNECTICUT

**COMMISSION ON CULTURE & TOURISM
STATE HISTORIC PRESERVATION OFFICE**

One Constitution Plaza, Second Floor, Hartford, CT 06103

HISTORIC RESOURCE INVENTORY FORM

For Buildings and Structures

CONTINUATION SHEET

Item Number: _____ Date: October 2011

PAL, Pawtucket, RI 02860

60 Jesup Road, Westport, CT

PHOTOGRAPHS

FOR OFFICE USE ONLY

TOWN NO.: _____ SITE NO.: _____

UTM: 18/____/____/____/____

QUAD: _____

DISTRICT: _____ NR: Actual
Potential



View of the northeast and northwest elevations.



View of southwest and southeast elevations.



HISTORIC RESOURCES INVENTORY - BUILDING AND STRUCTURES

Please send completed form to: Stacey Vairo, National Register and State Register Coordinator,
Connecticut Commission on Culture & Tourism, One Constitution Plaza, 2nd Floor, Hartford, CT 06103

* Note: Please attach any additional or expanded information on a separate sheet.

GENERAL INFORMATION

Building Name (Common) _____
 Building Name (Historic) Godillot Carriage House
 Street Address or Location 61 Jesup Road
 Town/City Westport Village _____ County Fairfield
 Owner(s) Tri-Town Teacher's Federal Credit Union Public Private

PROPERTY INFORMATION

Present Use: Commercial
 Historic Use: Carriage House
 Accessibility to public: Exterior visible from public road? Yes No
 Interior accessible? Yes No If yes, explain _____
 Style of building Stick Style Date of Construction 1882

Material(s) (Indicate use or location when appropriate):

- | | | | | |
|--|---|---|--|--|
| <input checked="" type="checkbox"/> Clapboard | <input type="checkbox"/> Asbestos Siding | <input checked="" type="checkbox"/> Brick | <input checked="" type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding |
| <input type="checkbox"/> Fieldstone | <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Stucco | <input type="checkbox"/> Cobblestone | <input type="checkbox"/> Aluminum Siding |
| <input type="checkbox"/> Concrete (Type _____) | <input type="checkbox"/> Cut Stone (Type _____) | <input type="checkbox"/> Other _____ | | |

Structural System

- Wood Frame Post & Beam Balloon Load bearing masonry Structural iron or steel
 Other _____

Roof (Type)

- Gable Flat Mansard Monitor Sawtooth
 Gambrel Shed Hip Round Other _____

(Material)

- Wood Shingle Roll Asphalt Tin Slate Asphalt Shingle
 Built up Tile Other _____

Number of Stories: 2.5 Approximate Dimensions _____

Structural Condition: Excellent Good Fair Deteriorated

Exterior Condition: Excellent Good Fair Deteriorated

Location Integrity: On original site Moved When? _____

Alterations? Yes No If yes, explain: Added cupola

FOR OFFICE USE: Town # _____ Site # _____ UTM _____

District: S NR If NR, Specify: Actual Potential

PROPERTY INFORMATION (CONT'D)

Related outbuildings or landscape features:

- Barn Shed Garage Carriage House Shop Garden
- Other landscape features or buildings: _____

Surrounding Environment:

- Open land Woodland Residential Commercial Industrial Rural
- High building density Scattered buildings visible from site

• Interrelationship of building and surroundings:

See Continuation Sheet

• Other notable features of building or site (*Interior and/or Exterior*)

See Continuation Sheet

Architect _____ Builder _____

• Historical or Architectural importance:

See Continuation Sheet

• Sources:

See Continuation Sheet

Photographer PAL _____ Date _____

View _____ Negative on File _____

Name _____ Date 12/13/2011

Organization PAL _____

Address 210 Lonsdale Avenue, Pawtucket, RI 02860

• Subsequent field evaluations:

Threats to the building or site:

- None known Highways Vandalism Developers Renewal Private
- Deterioration Zoning Other _____ Explanation _____

STATE OF CONNECTICUT

**COMMISSION ON CULTURE & TOURISM
STATE HISTORIC PRESERVATION OFFICE**
One Constitution Plaza, Second Floor, Hartford, CT 06103

FOR OFFICE USE ONLY	
TOWN NO.:	SITE NO.:
UTM: 18/	/ / / / / / / /
QUAD:	
DISTRICT:	NR: Actual Potential

HISTORIC RESOURCE INVENTORY FORM
For Buildings and Structures

CONTINUATION SHEET

Item Number: _____ Date: October 2011
PAL, Pawtucket, RI 02860

61 Jesup Road, Westport, CT

Interrelationship of building and surroundings:

The building is located on a sloping site on the northeast side of Jesup Road. It is set close to the road and faces south. Landscaped beds and large hedges surround the building. A level, grassy area bisected by a brick pathway lies to the east of the building. An asphalt driveway leads from Jesup Road to the basement level of the building's north elevation. A large parking area is located to the west of the building and features an at-grade entrance to the building's ground floor.

Other notable features of building or site (*Interior and/or Exterior*):

The building is a two-and-one-half-story, three-bay-by-three-bay, former carriage house and stable constructed in the Stick Style. It has a wood shingle-clad, front-gable roof with clipped gables. A cross gable is located in the center of the south elevation, and a cupola sits at the center of the ridge. The gables contain pent roofs with brackets and wide solid vergeboard. The gables on the west (facade) and east elevations have large corner brackets. The walls are clad with clapboard on the first story and scalloped wood shingle on the second story divided by a wide, horizontal, wood trim band and rest on a brick foundation. The building was built into a steep slope providing for a full-height basement level on the south and east elevations. The primary entrances are located on the north and south ends of the facade and consist of wood panel doors with solid transoms and flat wood trim. A secondary entrance is located off-center in the basement level of the south elevation and contains a similar wood panel door, but the wood panels in the top half were replaced with glass. Original carriage entrances in the center of the facade and basement level of the south elevation still retain the wood panel doors but are now inoperable. The carriage entrance door in the center of the facade also had the upper wood panels replaced with glass. A loft door in the center of the gable on the facade appears original to the building, but was also made inoperable. An original loft door located in the center of the gable on the south elevation had the wood panels replaced with glass. Windows consist of two-over-two, double-hung sash with flat wood trim and wood panels above. Window openings in the basement level have segmental arched, two-over-two, double-hung sash with splayed brick lintels and granite sills. The building plan and architectural features are intact. Minimal alterations consist of modifying the functionality of some original doors and replacing some exterior cladding.

Historical or Architectural importance:

The building was constructed in 1882 by Alexis and Julia Godillot Jr. as a carriage house for the residence at 60 Jesup Road. Godillot, who owned a French import business, had purchased the main house in 1879. In 1882, he greatly expanding the house and constructing the carriage house as well as a boathouse and servant's quarters. In 1901, the property was transferred to the Godillot's son, lawyer John F. Godillot. In 1920, the lot was sold to Elizabeth Lyman, a nurse at the Westport Sanatorium, who converted the buildings into boarding houses. In 1951, the property was purchased by the Town of Westport and the residence was renovated to serve as offices for the Board of Education. During this time, the carriage house appears to have been used as a maintenance building. The property was sold in the early 1980s, and the residence continued to be used for offices. By 1991, the carriage house was occupied by its current owner, Tri-Town Teacher's Federal Credit Union.

Sources:

Brown, T. Robins. Godillot Place NR. Hartford: CT Historical Commission, 1977; Westport Directory (W.D.).
Loveland, CO: US West Marketing Resources, 1991; W.D. Chicago, IL: Johnson Publishing Co., 1985; W.D.
Providence, RI: C. DeWitt White Co., 1917-1918; W.D. New Haven: The Price & Lee Co., 1923-1974; Westport Assessor's Online Database, 2011.

STATE OF CONNECTICUT

**COMMISSION ON CULTURE & TOURISM
STATE HISTORIC PRESERVATION OFFICE**
One Constitution Plaza, Second Floor, Hartford, CT 06103

HISTORIC RESOURCE INVENTORY FORM
For Buildings and Structures

CONTINUATION SHEET

Item Number: _____ Date: October 2011

PAL, Pawtucket, RI 02860

61 Jesup Road, Westport, CT

PHOTOGRAPHS

<i>FOR OFFICE USE ONLY</i>	
TOWN NO.:	SITE NO.:
UTM: 18/	/ / / / /
QUAD:	
DISTRICT:	NR: Actual Potential



View of the south and east elevations.



View of the south and west elevations.

STATE OF CONNECTICUT

**COMMISSION ON CULTURE & TOURISM
STATE HISTORIC PRESERVATION OFFICE**
One Constitution Plaza, Second Floor, Hartford, CT 06103

HISTORIC RESOURCE INVENTORY FORM
For Buildings and Structures

CONTINUATION SHEET

Item Number: _____ Date: October 2011

PAL, Pawtucket, RI 02860

61 Jesup Road, Westport, CT

FOR OFFICE USE ONLY

TOWN NO.: _____ SITE NO.: _____
UTM: 18/____/____/____/____/____
QUAD: _____
DISTRICT: _____ NR: Actual
Potential



View of the west elevation.



HISTORIC RESOURCES INVENTORY - BUILDING AND STRUCTURES

Please send completed form to: Stacey Vairo, National Register and State Register Coordinator,
Connecticut Commission on Culture & Tourism, One Constitution Plaza, 2nd Floor, Hartford, CT 06103

* Note: Please attach any additional or expanded information on a separate sheet.

GENERAL INFORMATION

Building Name (Common) _____
 Building Name (Historic) Godillot Servants' Quarters
 Street Address or Location 65 Jesup Road
 Town/City Westport Village _____ County Fairfield
 Owner(s) Godillot Associates Public Private

PROPERTY INFORMATION

Present Use: Commercial
 Historic Use: Servant's Quarters
 Accessibility to public: Exterior visible from public road? Yes No
 Interior accessible? Yes No If yes, explain _____
 Style of building Queen Anne Date of Construction 1882

Material(s) (Indicate use or location when appropriate):

- | | | | | |
|---|---|---|--|--|
| <input checked="" type="checkbox"/> Clapboard | <input type="checkbox"/> Asbestos Siding | <input checked="" type="checkbox"/> Brick | <input checked="" type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding |
| <input checked="" type="checkbox"/> Fieldstone | <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Stucco | <input type="checkbox"/> Cobblestone | <input type="checkbox"/> Aluminum Siding |
| <input checked="" type="checkbox"/> Concrete (Type <u>Block</u>) | <input type="checkbox"/> Cut Stone (Type _____) | <input type="checkbox"/> Other _____ | | |

Structural System

- Wood Frame Post & Beam Balloon Load bearing masonry Structural iron or steel
 Other _____

Roof (Type)

- Gable Flat Mansard Monitor Sawtooth
 Gambrel Shed Hip Round Other _____

(Material)

- Wood Shingle Roll Asphalt Tin Slate Asphalt Shingle
 Built up Tile Other _____

Number of Stories: 2 Approximate Dimensions _____

Structural Condition: Excellent Good Fair Deteriorated

Exterior Condition: Excellent Good Fair Deteriorated

Location Integrity: On original site Moved When? _____

Alterations? Yes No If yes, explain: Side addition

FOR OFFICE USE: Town # _____ Site # _____ UTM _____

District: S NR If NR, Specify: Actual Potential

PROPERTY INFORMATION (CONT'D)

Related outbuildings or landscape features:

- Barn Shed Garage Carriage House Shop Garden
- Other landscape features or buildings: _____

Surrounding Environment:

- Open land Woodland Residential Commercial Industrial Rural
- High building density Scattered buildings visible from site

• Interrelationship of building and surroundings:

See Continuation Sheet

• Other notable features of building or site (*Interior and/or Exterior*)

See Continuation Sheet

Architect _____ Builder _____

• Historical or Architectural importance:

See Continuation Sheet

• Sources:

See Continuation Sheet

Photographer PAL _____ Date _____

View _____ Negative on File _____

Name _____ Date 12/13/2011

Organization PAL _____

Address 210 Lonsdale Avenue, Pawtucket, RI 02860

• Subsequent field evaluations:

Threats to the building or site:

- None known Highways Vandalism Developers Renewal Private
- Deterioration Zoning Other _____ Explanation _____

STATE OF CONNECTICUT

**COMMISSION ON CULTURE & TOURISM
STATE HISTORIC PRESERVATION OFFICE**
One Constitution Plaza, Second Floor, Hartford, CT 06103

FOR OFFICE USE ONLY	
TOWN NO.:	SITE NO.:
UTM: 18/	/ / / / / / / /
QUAD:	
DISTRICT:	NR: Actual Potential

HISTORIC RESOURCE INVENTORY FORM
For Buildings and Structures

CONTINUATION SHEET

Item Number: _____ Date: October 2011
PAL, Pawtucket, RI 02860

65 Jesup Road, Westport, CT

Interrelationship of building and surroundings:

The building is located on a sloping site on the northeast side of Jesup Road. It is set close to the road and faces south. Landscaped beds and large shrubs surround the building. A fieldstone retaining wall borders the cement sidewalk that extends across the north side of the property. A level, grassy area bisected by a brick pathway lies to the west of the building. A stream runs along the north and east boundaries of the lot and is lined by fieldstone walls that also serve as a retaining wall and foundation on the north side of the building.

Other notable features of building or site (*Interior and/or Exterior*):

The building is a two-story, four-bay-by-three-bay, former servant’s quarters constructed in the Queen Anne style. It has an asphalt shingle-clad, front-gable roof with a brick chimney at the center of the roof and a molded cornice. The gable on the south (facade) elevation has a pent roof with brackets, wide, flat vergeboards, and a decorative truss. The walls are clad with clapboard on the first floor and with decorative wood single on the second story and a rest on brick foundation. The building was constructed into a steep slope providing for a full-height basement level on the north and east elevations. A two-story ell, contemporary to the original construction of the building, is located on the north (rear) elevation. The ell has a gable roof, clapboard-clad walls, and a stone foundation. The stone foundation is also a portion of the wall that lines the banks of the stream that runs on the north and east sides of the property. A one-and-one-half-story addition on the west elevation of the main block of the house replaced the original greenhouse. The addition has an asphalt-clad, side-gable roof with full-width shed dormers on the north and south slopes, clapboard siding, and a concrete foundation. A one-story addition is located at the junction of the north ell and west addition. The full-width porch has a hip roof supported by posts and a railing with turned spindles. The porch roof wraps around the east elevation and is supported by two-story posts covering a brick patio. A gable-roof bay window on the second story projects over the first story in the center of the east elevation. The primary entrance is located off-center on the facade and consists of a wood panel door with simple wood trim and heavy lintel. Secondary entrances are located on the east elevation of the one-story addition and the basement level on the east elevation of the main block. Windows consist of six-over-six, double-hung, mid-twentieth-century replacement sash in varying sizes. Windows in the main block of the house have wide, flat wood trim and heavy lintels. The building remains relatively intact, including its plan and architectural details. The only major alteration was the removal of the original greenhouse and replacing it with the current east addition. Minor alterations consist of replacement windows and exterior cladding.

Historical or Architectural importance:

The building was constructed ca. 1882 by Alexis and Julia Godillot Jr. as servant’s quarters for the residence at 60 Jesup Road. Godillot, who owned a French import business, purchased the residence in 1879. In 1882, he greatly expanding the house and constructing the servant’s quarters as well as a boathouse and carriage house. In 1901, the property was transferred to the Godillot’s son, lawyer John F. Godillot. In 1920 the lot was sold to Elizabeth Lyman, a nurse at the Westport Sanatorium, who converted the buildings into boarding houses. In 1951, the property was purchased by the Town of Westport; and the residence was renovated to serve as offices for the Board of Education. In 1980, the lot was listed as vacant; and by 1985 the carriage house contained a business called Promotional Marketing Corp. Six years later, the building held the law offices of Sherwood, Garlick, Cowell, Diviny & Atwood and four personal offices. Currently, the building is owned by Godillot Associates and is occupied by a law office.

Sources:

Brown, T. Robins. Godillot Place NR. Hartford: CT Historical Commission, 1977; Westport Directory (W.D.).
Loveland, CO: US West Marketing Resources, 1991; W.D. Chicago, IL: Johnson Publishing Co., 1985; W.D.
Providence, RI: C. DeWitt White Co., 1917-1918; W.D. New Haven: The Price & Lee Co., 1923-1974; Westport

STATE OF CONNECTICUT

**COMMISSION ON CULTURE & TOURISM
STATE HISTORIC PRESERVATION OFFICE**

One Constitution Plaza, Second Floor, Hartford, CT 06103

HISTORIC RESOURCE INVENTORY FORM

For Buildings and Structures

CONTINUATION SHEET

Item Number: _____ Date: October 2011

Assessor's Online Database, 2011.

FOR OFFICE USE ONLY

TOWN NO.: _____ SITE NO.: _____

UTM: 18/____/____/____/____/____

QUAD: _____

DISTRICT: _____ NR: Actual
Potential

STATE OF CONNECTICUT

**COMMISSION ON CULTURE & TOURISM
STATE HISTORIC PRESERVATION OFFICE**
One Constitution Plaza, Second Floor, Hartford, CT 06103

<i>FOR OFFICE USE ONLY</i>	
TOWN NO.:	SITE NO.:
UTM: 18/	/ / / / /
QUAD:	
DISTRICT:	NR: Actual Potential

HISTORIC RESOURCE INVENTORY FORM
For Buildings and Structures

CONTINUATION SHEET

Item Number: _____ Date: October 2011
PAL, Pawtucket, RI 02860

65 Jesup Road, Westport, CT

PHOTOGRAPHS



View of the south and west elevations.



View of the south elevation.

STATE OF CONNECTICUT

**COMMISSION ON CULTURE & TOURISM
STATE HISTORIC PRESERVATION OFFICE**

One Constitution Plaza, Second Floor, Hartford, CT 06103

HISTORIC RESOURCE INVENTORY FORM

For Buildings and Structures

CONTINUATION SHEET

Item Number: _____ Date: October 2011

PAL, Pawtucket, RI 02860

65 Jesup Road, Westport, CT

FOR OFFICE USE ONLY

TOWN NO.: _____ SITE NO.: _____

UTM: 18/____/____/____/____/____

QUAD: _____

DISTRICT: _____ NR: Actual
Potential



View of the south and east elevations.



HISTORIC RESOURCES INVENTORY - BUILDING AND STRUCTURES

Please send completed form to: Stacey Vairo, National Register and State Register Coordinator,
Connecticut Commission on Culture & Tourism, One Constitution Plaza, 2nd Floor, Hartford, CT 06103

* Note: Please attach any additional or expanded information on a separate sheet.

GENERAL INFORMATION

Building Name (Common) Jesup Road Bridge

Building Name (Historic) _____

Street Address or Location Jesup Road, directly west of the intersection with Imperial Avenue

Town/City Westport Village _____ County Fairfield

Owner(s) _____ Public Private

PROPERTY INFORMATION

Present Use: Transportation

Historic Use: Transportation

Accessibility to public: Exterior visible from public road? Yes No

Interior accessible? Yes No If yes, explain _____

Style of building _____ Date of Construction ca. 1950

Material(s) (Indicate use or location when appropriate):

- | | | | | |
|--|---|--------------------------------------|---------------------------------------|--|
| <input type="checkbox"/> Clapboard | <input type="checkbox"/> Asbestos Siding | <input type="checkbox"/> Brick | <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding |
| <input checked="" type="checkbox"/> Fieldstone | <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Stucco | <input type="checkbox"/> Cobblestone | <input type="checkbox"/> Aluminum Siding |
| <input checked="" type="checkbox"/> Concrete (Type <u>Precast deck</u>) | <input type="checkbox"/> Cut Stone (Type _____) | <input type="checkbox"/> Other _____ | | |

Structural System

- Wood Frame Post & Beam Balloon Load bearing masonry Structural iron or steel
 Other _____

Roof (Type)

- Gable Flat Mansard Monitor Sawtooth
 Gambrel Shed Hip Round Other _____

(Material)

- Wood Shingle Roll Asphalt Tin Slate Asphalt Shingle
 Built up Tile Other _____

Number of Stories: _____ Approximate Dimensions _____

Structural Condition: Excellent Good Fair Deteriorated

Exterior Condition: Excellent Good Fair Deteriorated

Location Integrity: On original site Moved When? _____

Alterations? Yes No If yes, explain: _____

FOR OFFICE USE: Town # _____ Site # _____ UTM _____

District: S NR If NR, Specify: Actual Potential

PROPERTY INFORMATION (CONT'D)

Related outbuildings or landscape features:

- Barn Shed Garage Carriage House Shop Garden
- Other landscape features or buildings: _____

Surrounding Environment:

- Open land Woodland Residential Commercial Industrial Rural
- High building density Scattered buildings visible from site

• Interrelationship of building and surroundings:

See continuation sheet.

• Other notable features of building or site (*Interior and/or Exterior*)

See continuation sheet.

Architect _____ Builder _____

• Historical or Architectural importance:

See continuation sheet.

• Sources:

See continuation sheet.

Photographer PAL _____ Date _____

View _____ Negative on File _____

Name _____ Date 12/13/2011

Organization PAL _____

Address 210 Lonsdale Avenue, Pawtucket, RI 02860

• Subsequent field evaluations:

Threats to the building or site:

- None known Highways Vandalism Developers Renewal Private
- Deterioration Zoning Other _____ Explanation _____

STATE OF CONNECTICUT

**COMMISSION ON CULTURE & TOURISM
STATE HISTORIC PRESERVATION OFFICE**

One Constitution Plaza, Second Floor, Hartford, CT 06103

HISTORIC RESOURCE INVENTORY FORM

For Buildings and Structures

CONTINUATION SHEET

Item Number: _____ Date: October 2011

PAL, Pawtucket, RI 02860

Jesup Road, directly west of the intersection with Imperial Avenue

Interrelation of building and surroundings:

The bridge is located on the west side of the intersection of Jesup Road and Imperial Avenue. Dead Man’s Brook runs beneath the bridge from the north. Jesup Road is edged by grassy lawns with natural tree cover. Imperial Avenue also has heavy vegetation surrounding the bridge.

Other notable features of building or site (*Interior and/or Exterior*):

The bridge is a single-arch span with built-up, split-faced granite and fieldstone abutments and wing walls. The abutment walls rise approximately a foot above the level of the road. The deck is composed of precast concrete edged by a low curb and measures approximately fifteen feet long and twenty-five feet wide. A concrete sidewalk runs along the north side of the bridge. Metal railings are attached to the top of the stone and deck.

Historical or Architectural importance:

The bridge was constructed ca. 1950 when Jesup Road was developed. Jesup Road was originally a nineteenth-century footpath with a wooden footbridge in the current concrete bridge’s location. The road bisected the Godilliot Place property to connect the south end of Bay Street with Imperial Avenue in the mid-twentieth century.

Sources:

Beers, J.H. & Co. Atlas of the County of Fairfield. 1867; Clark, Richard. Fairfield County, Connecticut. 1855; Hopkins, G.M. Atlas of the County of Fairfield. 1879; Malm, Dorothea. Westport, Connecticut, 1842. 2000; Sanborn Fire Insurance Maps. 1891-1940.

<i>FOR OFFICE USE ONLY</i>	
TOWN NO.:	SITE NO.:
UTM: 18/	/ / / / / / / /
QUAD:	
DISTRICT:	NR: Actual Potential

STATE OF CONNECTICUT

**COMMISSION ON CULTURE & TOURISM
STATE HISTORIC PRESERVATION OFFICE**
One Constitution Plaza, Second Floor, Hartford, CT 06103

HISTORIC RESOURCE INVENTORY FORM
For Buildings and Structures

CONTINUATION SHEET

Item Number: _____ Date: October 2011
PAL, Pawtucket, RI 02860

Jesup Road, directly west of the intersection with Imperial Avenue

PHOTOGRAPHS

<i>FOR OFFICE USE ONLY</i>	
TOWN NO.:	SITE NO.:
UTM: 18/ / / / / / / /	
QUAD:	
DISTRICT:	NR: Actual Potential



View looking north at south face of bridge.



View looking east towards Imperial Avenue.