



## HISTORIC RESOURCES INVENTORY - BUILDING AND STRUCTURES

Please send completed form to: Stacey Vairo, National Register and State Register Coordinator,  
Connecticut Commission on Culture & Tourism, One Constitution Plaza, 2nd Floor, Hartford, CT 06103

\* Note: Please attach any additional or expanded information on a separate sheet.

### GENERAL INFORMATION

Building Name (Common) \_\_\_\_\_

Building Name (Historic) \_\_\_\_\_

Street Address or Location 18 Riverside Avenue

Town/City Westport Village \_\_\_\_\_ County Fairfield

Owner(s) Wong Cheung Cheun  Public  Private

### PROPERTY INFORMATION

Present Use: Commercial

Historic Use: Commercial

Accessibility to public: Exterior visible from public road?  Yes  No

Interior accessible?  Yes  No If yes, explain \_\_\_\_\_

Style of building Vernacular Date of Construction ca. 1930

Material(s) (Indicate use or location when appropriate):

- |  |   |   |                                       |  |
|--|---|---|---------------------------------------|--|
| <input type="checkbox"/> Clapboard             | <input type="checkbox"/> Asbestos Siding        | <input checked="" type="checkbox"/> Brick                           | <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding  |
| <input type="checkbox"/> Fieldstone            | <input type="checkbox"/> Board & Batten         | <input type="checkbox"/> Stucco                                     | <input type="checkbox"/> Cobblestone  | <input type="checkbox"/> Aluminum Siding |
| <input type="checkbox"/> Concrete (Type _____) | <input type="checkbox"/> Cut Stone (Type _____) | <input checked="" type="checkbox"/> Other <u>Vert. board siding</u> |                                       |  |

### Structural System

- Wood Frame  Post & Beam  Balloon  Load bearing masonry  Structural iron or steel  
 Other \_\_\_\_\_

### Roof (Type)

- Gable  Flat  Mansard  Monitor  Sawtooth  
 Gambrel  Shed  Hip  Round  Other \_\_\_\_\_

### (Material)

- Wood Shingle  Roll Asphalt  Tin  Slate  Asphalt Shingle  
 Built up  Tile  Other Not visible

Number of Stories: 2 Approximate Dimensions \_\_\_\_\_

Structural Condition:  Excellent  Good  Fair  Deteriorated

Exterior Condition:  Excellent  Good  Fair  Deteriorated

Location Integrity:  On original site  Moved When? \_\_\_\_\_

Alterations?  Yes  No If yes, explain: Storefront

**FOR OFFICE USE:** Town # \_\_\_\_\_ Site # \_\_\_\_\_ UTM \_\_\_\_\_

District:  S  NR If NR, Specify:  Actual  Potential

**PROPERTY INFORMATION (CONT'D)**

**Related outbuildings or landscape features:**

- Barn       Shed       Garage       Carriage House       Shop       Garden
- Other landscape features or buildings: \_\_\_\_\_

**Surrounding Environment:**

- Open land     Woodland     Residential     Commercial     Industrial     Rural
- High building density       Scattered buildings visible from site

• Interrelationship of building and surroundings:

See Continuation Sheet

• Other notable features of building or site (*Interior and/or Exterior*)

See Continuation Sheet

Architect \_\_\_\_\_ Builder \_\_\_\_\_

• Historical or Architectural importance:

See Continuation Sheet

• Sources:

See Continuation Sheet

Photographer PAL \_\_\_\_\_ Date \_\_\_\_\_

View \_\_\_\_\_ Negative on File \_\_\_\_\_

Name \_\_\_\_\_ Date 12/13/2011

Organization PAL \_\_\_\_\_

Address 210 Lonsdale Avenue, Pawtucket, RI 02860

• Subsequent field evaluations:

**Threats to the building or site:**

- None known       Highways       Vandalism       Developers       Renewal       Private
- Deterioration       Zoning       Other \_\_\_\_\_       Explanation \_\_\_\_\_

**STATE OF CONNECTICUT**

**COMMISSION ON CULTURE & TOURISM  
STATE HISTORIC PRESERVATION OFFICE**  
One Constitution Plaza, Second Floor, Hartford, CT 06103

FOR OFFICE USE ONLY

TOWN NO.:            SITE NO.:  
UTM: 18/\_\_\_/\_\_\_/\_\_\_/\_\_\_/\_\_\_  
QUAD:  
DISTRICT:            NR: Actual  
  Potential

**HISTORIC RESOURCE INVENTORY FORM**  
For Buildings and Structures

**CONTINUATION SHEET**

Item Number: \_\_\_\_\_ Date: October 2011  
PAL, Pawtucket, RI 02860

**18 Riverside Avenue, Westport, CT**

**Interrelationship of building and surroundings:**

The building is sited on a level lot on the west side of Riverside Avenue. It sits close to the street and faces east. A sidewalk runs along the building’s east (facade) and a stone-lined bed containing grass and a large shrub lies directly to the north of the building. A parking lot set several feet above the level of Riverside Avenue and supported by a wooden retaining wall occupies the property behind the building.

**Other notable features of building or site (*Interior and/or Exterior*):**

The commercial building is two stories tall, three bays wide, two bays deep, and constructed in the vernacular style. The rolled asphalt-clad shed roof has stepped parapets on the north elevation and an interior brick chimney near the west elevation. The south end of the building was originally constructed as a store addition to the original dwelling on the lot. By the early 1930s, a second addition was constructed on the north end of the building. The original dwelling was demolished by 1940. The north and west elevations are brick and feature brick lintels over the windows. The east (facade) and south elevations are clad in vertical board with a flat cornice boards. The two main entrances are located on the northeast elevation and consist of modern, board-and-batten wood doors. Windows are a combination of one-over-one, double-hung vinyl and plate glass replacement sash and are set in simple wood surrounds. Modern alterations to the building include the replacement of the windows as well as the storefronts and siding on the facade.

**Historical or Architectural importance:**

The current building was constructed ca. 1930 as a storefront addition onto a ca. 1895 residence. By 1941, the original dwelling had been destroyed, leaving only the more recent storefront. The address appears in the 1948 directory as Superior Cleaners & Dryers. The cleaners remained until the mid 1950s, and by 1960 the building was occupied by dressmaker A. Husko. The building was listed as vacant in the 1965 directory and over the following two decades the address was not included in directories. By 1991, Monceau Park was listed as the sole tenant at the address. Currently the building is owned by Wong Cheung Cheun and contains retail space on the ground floor and living space on the upper story.

**Sources:**

Sanborn Fire Insurance Maps. 1891-1940; Westport Directory (W.D.). Loveland, CO: US West Marketing Resources, 1991; W.D. Chicago, IL: Johnson Publishing Co., 1985; W.D. Providence, RI: C. DeWitt White Co., 1917-1918; W.D. New Haven: The Price & Lee Co., 1923-1974; Westport Assessor’s Online Database, 2011.

**STATE OF CONNECTICUT**

**COMMISSION ON CULTURE & TOURISM  
STATE HISTORIC PRESERVATION OFFICE**  
One Constitution Plaza, Second Floor, Hartford, CT 06103

<i>FOR OFFICE USE ONLY</i>	
TOWN NO.:	SITE NO.:
UTM: 18/	/ / / / /
QUAD:	
DISTRICT:	NR: Actual Potential

**HISTORIC RESOURCE INVENTORY FORM**  
For Buildings and Structures

**CONTINUATION SHEET**

Item Number: \_\_\_\_\_ Date: October 2011

**PAL, Pawtucket, RI 02860**

**18 Riverside Avenue, Westport, CT**

**PHOTOGRAPHS**



View of the east and north elevations.



View of the east and south elevations.



## HISTORIC RESOURCES INVENTORY - BUILDING AND STRUCTURES

Please send completed form to: Stacey Vairo, National Register and State Register Coordinator,  
Connecticut Commission on Culture & Tourism, One Constitution Plaza, 2nd Floor, Hartford, CT 06103

\* Note: Please attach any additional or expanded information on a separate sheet.

### GENERAL INFORMATION

Building Name (Common) \_\_\_\_\_

Building Name (Historic) \_\_\_\_\_

Street Address or Location 22 Riverside Avenue

Town/City Westport Village \_\_\_\_\_ County Fairfield

Owner(s) Pepper Partners LLC  Public  Private

### PROPERTY INFORMATION

Present Use: Commercial

Historic Use: Commercial

Accessibility to public: Exterior visible from public road?  Yes  No

Interior accessible?  Yes  No If yes, explain \_\_\_\_\_

Style of building Vernacular Date of Construction ca. 1920

Material(s) (Indicate use or location when appropriate):

- |  |   |   |                                       |  |
|--|---|---|---------------------------------------|--|
| <input type="checkbox"/> Clapboard             | <input type="checkbox"/> Asbestos Siding        | <input checked="" type="checkbox"/> Brick | <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding  |
| <input type="checkbox"/> Fieldstone            | <input type="checkbox"/> Board & Batten         | <input type="checkbox"/> Stucco           | <input type="checkbox"/> Cobblestone  | <input type="checkbox"/> Aluminum Siding |
| <input type="checkbox"/> Concrete (Type _____) | <input type="checkbox"/> Cut Stone (Type _____) | <input type="checkbox"/> Other _____      |                                       |  |

#### Structural System

- Wood Frame  Post & Beam  Balloon  Load bearing masonry  Structural iron or steel  
 Other \_\_\_\_\_

#### Roof (Type)

- Gable  Flat  Mansard  Monitor  Sawtooth  
 Gambrel  Shed  Hip  Round  Other \_\_\_\_\_

#### (Material)

- Wood Shingle  Roll Asphalt  Tin  Slate  Asphalt Shingle  
 Built up  Tile  Other Not visible

Number of Stories: 1 Approximate Dimensions \_\_\_\_\_

Structural Condition:  Excellent  Good  Fair  Deteriorated

Exterior Condition:  Excellent  Good  Fair  Deteriorated

Location Integrity:  On original site  Moved When? \_\_\_\_\_

Alterations?  Yes  No If yes, explain: \_\_\_\_\_

**FOR OFFICE USE:** Town # \_\_\_\_\_ Site # \_\_\_\_\_ UTM \_\_\_\_\_

District:  S  NR If NR, Specify:  Actual  Potential

**PROPERTY INFORMATION (CONT'D)**

**Related outbuildings or landscape features:**

- Barn       Shed       Garage       Carriage House       Shop       Garden
- Other landscape features or buildings: \_\_\_\_\_

**Surrounding Environment:**

- Open land     Woodland     Residential     Commercial     Industrial     Rural
- High building density       Scattered buildings visible from site

• Interrelationship of building and surroundings:

• Other notable features of building or site (*Interior and/or Exterior*)

Architect \_\_\_\_\_ Builder \_\_\_\_\_

• Historical or Architectural importance:

• Sources:

Photographer PAL \_\_\_\_\_ Date \_\_\_\_\_

View \_\_\_\_\_ Negative on File \_\_\_\_\_

Name \_\_\_\_\_ Date 12/13/2011

Organization PAL \_\_\_\_\_

Address 210 Lonsdale Avenue, Pawtucket, RI 02860

• Subsequent field evaluations:

**Threats to the building or site:**

- None known       Highways       Vandalism       Developers       Renewal       Private
- Deterioration       Zoning       Other \_\_\_\_\_       Explanation \_\_\_\_\_

**STATE OF CONNECTICUT**

**COMMISSION ON CULTURE & TOURISM  
STATE HISTORIC PRESERVATION OFFICE**  
One Constitution Plaza, Second Floor, Hartford, CT 06103

FOR OFFICE USE ONLY

TOWN NO.:            SITE NO.:  
UTM: 18/\_\_\_/\_\_\_/\_\_\_/\_\_\_/\_\_\_  
QUAD:  
DISTRICT:            NR: Actual  
                                 Potential

**HISTORIC RESOURCE INVENTORY FORM**  
For Buildings and Structures

**CONTINUATION SHEET**

Item Number: \_\_\_\_\_ Date: October 2011  
PAL, Pawtucket, RI 02860

**22 Riverside Avenue, Westport, CT**

**Interrelationship of building and surroundings:**

The building occupies a level lot on the west side of Riverside Avenue. It is set close to the street and faces east. The south side of the building is lined by shrubs and a parking area is located on the north side of the property. Several tall trees border the west edge of the lot.

**Other notable features of building or site (*Interior and/or Exterior*):**

The building is a one-story, four-bay-by-one-bay commercial space. The west end of the building is constructed into a steep embankment. The flat roof is edged by a brick parapet on the east (facade) elevation. The north and south elevations are concrete block and the facade is faced with brick with a simple corbelled cornice below the parapet. There are two identical entrances on the facade consisting modern, partially-glazed panel doors with single-light transoms. Two large, fixed sash windows with slightly projecting brick sills are also located on the facade. The building’s plan is intact and, aside from the replacement doors and windows on the facade, the materials appear original.

**Historical or Architectural importance:**

Although the property record card lists a construction date of 1920, the building is not visible on a map of the area until the 1940 Sanborn map, where it is depicted at twice its current size. The 1941 and 1946 directories listed the property as vacant, and by 1948 the building was occupied by Superior Cleaners and Dryers. The cleaners remained at the address through the mid 1950s, and by 1960 Television Workshop Inc. had moved into the space. In 1965 the building was occupied by Chuckta Catering Services and in 1978 the property was purchased by Ernest A. Wiehl, Jr. The caterers were listed at the address through the 1990s and in 2005 the building sold to current owners Pepper Partners LLC. The building now houses an upholsterer.

**Sources:**

Westport Directory (W.D.). Loveland, CO: US West Marketing Resources, 1991; W.D. Chicago, IL: Johnson Publishing Co., 1985; W.D. New Haven: The Price & Lee Co., 1923-1974; Westport Assessor’s Online Database, 2012.

**STATE OF CONNECTICUT**

**COMMISSION ON CULTURE & TOURISM  
STATE HISTORIC PRESERVATION OFFICE**  
One Constitution Plaza, Second Floor, Hartford, CT 06103

**HISTORIC RESOURCE INVENTORY FORM**  
For Buildings and Structures

**CONTINUATION SHEET**

Item Number: \_\_\_\_\_ Date: October 2011  
PAL, Pawtucket, RI 02860  
22 Riverside Avenue, Westport, CT

**PHOTOGRAPHS**

<i>FOR OFFICE USE ONLY</i>	
TOWN NO.:	SITE NO.:
UTM: 18/___/___/___/___	
QUAD:	
DISTRICT:	NR: Actual Potential



View of the north and east elevations.



View of the east elevation.





## HISTORIC RESOURCES INVENTORY - BUILDING AND STRUCTURES

Please send completed form to: Stacey Vairo, National Register and State Register Coordinator,  
Connecticut Commission on Culture & Tourism, One Constitution Plaza, 2nd Floor, Hartford, CT 06103

\* Note: Please attach any additional or expanded information on a separate sheet.

### GENERAL INFORMATION

Building Name (Common) \_\_\_\_\_

Building Name (Historic) \_\_\_\_\_

Street Address or Location 42 Riverside Avenue

Town/City Westport Village \_\_\_\_\_ County Fairfield

Owner(s) Dennis and Richard Grimaldi  Public  Private

### PROPERTY INFORMATION

Present Use: Commercial

Historic Use: Commercial

Accessibility to public: Exterior visible from public road?  Yes  No

Interior accessible?  Yes  No If yes, explain \_\_\_\_\_

Style of building Vernacular Date of Construction ca. 1940

Material(s) (Indicate use or location when appropriate):

- |  |   |   |                                       |  |
|--|---|---|---------------------------------------|--|
| <input type="checkbox"/> Clapboard             | <input type="checkbox"/> Asbestos Siding        | <input checked="" type="checkbox"/> Brick | <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding  |
| <input type="checkbox"/> Fieldstone            | <input type="checkbox"/> Board & Batten         | <input type="checkbox"/> Stucco           | <input type="checkbox"/> Cobblestone  | <input type="checkbox"/> Aluminum Siding |
| <input type="checkbox"/> Concrete (Type _____) | <input type="checkbox"/> Cut Stone (Type _____) | <input type="checkbox"/> Other _____      |                                       |  |

### Structural System

- Wood Frame  Post & Beam  Balloon  Load bearing masonry  Structural iron or steel  
 Other \_\_\_\_\_

### Roof (Type)

- Gable  Flat  Mansard  Monitor  Sawtooth  
 Gambrel  Shed  Hip  Round  Other \_\_\_\_\_

### (Material)

- Wood Shingle  Roll Asphalt  Tin  Slate  Asphalt Shingle  
 Built up  Tile  Other Not visible

Number of Stories: 2 Approximate Dimensions \_\_\_\_\_

Structural Condition:  Excellent  Good  Fair  Deteriorated

Exterior Condition:  Excellent  Good  Fair  Deteriorated

Location Integrity:  On original site  Moved When? \_\_\_\_\_

Alterations?  Yes  No If yes, explain: \_\_\_\_\_

**FOR OFFICE USE:** Town # \_\_\_\_\_ Site # \_\_\_\_\_ UTM \_\_\_\_\_

District:  S  NR If NR, Specify:  Actual  Potential

**PROPERTY INFORMATION (CONT'D)**

**Related outbuildings or landscape features:**

- Barn       Shed       Garage       Carriage House       Shop       Garden
- Other landscape features or buildings: \_\_\_\_\_

**Surrounding Environment:**

- Open land     Woodland     Residential     Commercial     Industrial     Rural
- High building density       Scattered buildings visible from site

• Interrelationship of building and surroundings:

See continuation sheet.

• Other notable features of building or site (*Interior and/or Exterior*)

See continuation sheet.

Architect \_\_\_\_\_ Builder \_\_\_\_\_

• Historical or Architectural importance:

See continuation sheet.

• Sources:

See continuation sheet.

Photographer PAL \_\_\_\_\_ Date \_\_\_\_\_

View \_\_\_\_\_ Negative on File \_\_\_\_\_

Name \_\_\_\_\_ Date 12/13/2011

Organization PAL \_\_\_\_\_

Address 210 Lonsdale Avenue, Pawtucket, RI 02860

• Subsequent field evaluations:

**Threats to the building or site:**

- None known       Highways       Vandalism       Developers       Renewal       Private
- Deterioration       Zoning       Other \_\_\_\_\_       Explanation \_\_\_\_\_

**STATE OF CONNECTICUT**

**COMMISSION ON CULTURE & TOURISM  
STATE HISTORIC PRESERVATION OFFICE**  
One Constitution Plaza, Second Floor, Hartford, CT 06103

<i>FOR OFFICE USE ONLY</i>	
TOWN NO.:	SITE NO.:
UTM: 18/	/ / / / / / / /
QUAD:	
DISTRICT:	NR: Actual Potential

**HISTORIC RESOURCE INVENTORY FORM**  
For Buildings and Structures

**CONTINUATION SHEET**

Item Number: \_\_\_\_\_ Date: October 2011  
PAL, Pawtucket, RI 02860

**42 Riverside Avenue, Westport, CT**

**Interrelationship of building and surroundings:**

The building occupies a level lot on the west side of Riverside Avenue. It is set close to the street and faces east. A parking area lies to the north of the building and several narrow parking spots line the building’s east elevation. Several tall trees border the south edge of the property.

**Other notable features of building or site (*Interior and/or Exterior*):**

The building is a two-story, four-bay-by-two-bay commercial space. The shed roof is edged by a parapet on the east (facade) elevation and brick chimney is attached to the west end of the south elevation. The walls are clad in brick in common bond. The main entrance is located on the facade and consists of a modern, fully-glazed door with a filled transom. The entrance is set within a cast-iron storefront that occupies the south half of the east elevation and consists of two molded panels and two large, plate glass windows. Above the entrance and windows and below the storefront’s wide cornice is a panel with raised gold lettering that reads “WESTPORT GLASS CO.” An overhead garage door is located in the north bay of the east elevation. Windows consist of one-over-one, double-hung wood sash set in wood frames with slightly projecting brick sills. Three rectangular, louvered wood vents with brick sills are located on the east elevation. The mid-twentieth-century plan is intact, although the windows and storefront appear to be replacements.

**Historical or Architectural importance:**

The property record card lists a construction date of 1934; however Sanborn maps indicate that an earlier dwelling on the lot remained until at least 1940 before it was replaced by the current store. It would appear that both the earlier building and present building were owned by Louis Sametz, who operated a celluloid goods business on the premises until the mid-1950s. In 1960, the store was occupied by Stephen S. Stahursky, but by 1965 present tenant Westport Glass Co. had moved into the space. The property was purchased by current owners Dennis and Richard Grimaldi in 1989.

**Sources:**

Sanborn Fire Insurance Maps. 1891-1940; Westport Directory (W.D.). Loveland, CO: US West Marketing Resources, 1991; W.D. Chicago, IL: Johnson Publishing Co., 1985; W.D. Providence, RI: C. DeWitt White Co., 1917-1918; W.D. New Haven: The Price & Lee Co., 1923-1974; Westport Assessor’s Online Database, 2012.

**STATE OF CONNECTICUT**

**COMMISSION ON CULTURE & TOURISM  
STATE HISTORIC PRESERVATION OFFICE**  
One Constitution Plaza, Second Floor, Hartford, CT 06103

**HISTORIC RESOURCE INVENTORY FORM**  
For Buildings and Structures

**CONTINUATION SHEET**

Item Number: \_\_\_\_\_ Date: October 2011  
PAL, Pawtucket, RI 02860

**42 Riverside Avenue, Westport, CT**

**PHOTOGRAPHS**



View of the east and south elevations.

*FOR OFFICE USE ONLY*

TOWN NO.: \_\_\_\_\_ SITE NO.: \_\_\_\_\_  
UTM: 18/\_\_\_\_/\_\_\_\_/\_\_\_\_/\_\_\_\_/\_\_\_\_  
QUAD: \_\_\_\_\_  
DISTRICT: \_\_\_\_\_ NR: Actual  
Potential



## HISTORIC RESOURCES INVENTORY - BUILDING AND STRUCTURES

Please send completed form to: Stacey Vairo, National Register and State Register Coordinator,  
Connecticut Commission on Culture & Tourism, One Constitution Plaza, 2nd Floor, Hartford, CT 06103

\* Note: Please attach any additional or expanded information on a separate sheet.

### GENERAL INFORMATION

Building Name (Common) \_\_\_\_\_  
 Building Name (Historic) Staples and Raymond Lumber and Building Materials  
 Street Address or Location 47 Riverside Avenue  
 Town/City Westport Village \_\_\_\_\_ County Fairfield  
 Owner(s) Sumaran Limited Partnership  Public  Private

### PROPERTY INFORMATION

Present Use: Commercial  
 Historic Use: Commercial  
 Accessibility to public: Exterior visible from public road?  Yes  No  
 Interior accessible?  Yes  No If yes, explain \_\_\_\_\_  
 Style of building Vernacular Date of Construction ca. 1890

Material(s) (Indicate use or location when appropriate):

- |   |   |   |                                       |  |
|---|---|---|---------------------------------------|--|
| <input type="checkbox"/> Clapboard                                | <input type="checkbox"/> Asbestos Siding        | <input type="checkbox"/> Brick                                  | <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding  |
| <input type="checkbox"/> Fieldstone                               | <input type="checkbox"/> Board & Batten         | <input type="checkbox"/> Stucco                                 | <input type="checkbox"/> Cobblestone  | <input type="checkbox"/> Aluminum Siding |
| <input checked="" type="checkbox"/> Concrete (Type <u>Block</u> ) | <input type="checkbox"/> Cut Stone (Type _____) | <input checked="" type="checkbox"/> Other <u>Plywood siding</u> |                                       |  |

### Structural System

- Wood Frame  Post & Beam  Balloon  Load bearing masonry  Structural iron or steel  
 Other \_\_\_\_\_

### Roof (Type)

- Gable  Flat  Mansard  Monitor  Sawtooth  
 Gambrel  Shed  Hip  Round  Other \_\_\_\_\_

(Material)

- Wood Shingle  Roll Asphalt  Tin  Slate  Asphalt Shingle  
 Built up  Tile  Other \_\_\_\_\_

Number of Stories: 2 Approximate Dimensions \_\_\_\_\_

Structural Condition:  Excellent  Good  Fair  Deteriorated

Exterior Condition:  Excellent  Good  Fair  Deteriorated

Location Integrity:  On original site  Moved When? \_\_\_\_\_

Alterations?  Yes  No If yes, explain: Multiple additions

**FOR OFFICE USE:** Town # \_\_\_\_\_ Site # \_\_\_\_\_ UTM \_\_\_\_\_

District:  S  NR If NR, Specify:  Actual  Potential

**PROPERTY INFORMATION (CONT'D)**

**Related outbuildings or landscape features:**

- Barn       Shed       Garage       Carriage House       Shop       Garden
- Other landscape features or buildings: \_\_\_\_\_

**Surrounding Environment:**

- Open land     Woodland     Residential     Commercial     Industrial     Rural
- High building density       Scattered buildings visible from site

• Interrelationship of building and surroundings:

See continuation sheet.

• Other notable features of building or site (*Interior and/or Exterior*)

See continuation sheet.

Architect \_\_\_\_\_ Builder \_\_\_\_\_

• Historical or Architectural importance:

See continuation sheet.

• Sources:

See continuation sheet.

Photographer PAL \_\_\_\_\_ Date \_\_\_\_\_

View \_\_\_\_\_ Negative on File \_\_\_\_\_

Name \_\_\_\_\_ Date 12/13/2011

Organization PAL \_\_\_\_\_

Address 210 Lonsdale Avenue, Pawtucket, RI 02860

• Subsequent field evaluations:

**Threats to the building or site:**

- None known       Highways       Vandalism       Developers       Renewal       Private
- Deterioration       Zoning       Other \_\_\_\_\_       Explanation \_\_\_\_\_

**STATE OF CONNECTICUT**

**COMMISSION ON CULTURE & TOURISM  
STATE HISTORIC PRESERVATION OFFICE**  
One Constitution Plaza, Second Floor, Hartford, CT 06103

FOR OFFICE USE ONLY

TOWN NO.:            SITE NO.:  
UTM: 18/\_\_\_/\_\_\_/\_\_\_/\_\_\_/\_\_\_  
QUAD:  
DISTRICT:            NR: Actual  
                                        Potential

**HISTORIC RESOURCE INVENTORY FORM**  
For Buildings and Structures

**CONTINUATION SHEET**

Item Number: \_\_\_\_\_ Date: October 2011  
PAL, Pawtucket, RI 02860

**47 Riverside Avenue, Westport, CT**

**Interrelationship of building and surroundings:**

The building is sited on a sloping lot on the east side of Riverside Avenue. It is set close to the street and faces east. Narrow alleys run between the several buildings on the lot. A large parking area runs the length of the east side of the property.

**Other notable features of building or site (*Interior and/or Exterior*):**

The building is comprised of three sections. The north section, the oldest portion, is a one-story, nine-bay-by-two-bay former lumber shed. The asphalt shingle-clad, side-gable roof has a deep overhang on the east elevation. The walls are clad in vertical-board siding and rest on a concrete block foundation. It was constructed into a steep slope providing for a full-height basement level on the east elevation. The oldest section of the building, the gable on the south end of the block, dates to before 1891, where it is visible on the 1891 Sanborn map as a lumber house. The entire building was converted into commercial spaces in the early 1960s. A wood porch set within the overhang on the east elevation is supported by wood posts and accessed by an exterior staircase on the north and south ends. There are three entrances on the west (facade) elevation and five on the east elevation, each consists of a partially-glazed metal door. The windows on the facade and north elevation consist of eight-over-eight double-hung sash arranged singularly and in pairs. The elevation has one-over-one, double-hung sash. Although the basic, late-nineteenth-century plan of the building appears relatively intact, when it was converted into commercial space the majority of the original north end lumber shed was enclosed. The materials date to either the time of the conversion in the mid-twentieth-century or are late-twentieth-century replacements.

The center block is a two-story, four-bay-by-three-bay early-twentieth-century vernacular building. The flat roof is surrounded by a parapet that wraps around all elevations. The walls are brick on the west (facade) elevation and clapboard on the north, south, and east elevations. The building was constructed into a steep slope providing for a full-height basement level on the east elevation. A one-story ell is attached to the south elevation has a brick facade and clapboard on the east elevation. A modern, metal frame sunroom is attached to the east end of the south elevation. The main entrance is located in a recessed bay off-center on the facade and consists of a partially-glazed, wood-panel door. A secondary entrance at the north end of the facade also consists of a glazed, wood-panel door. Windows primarily consist of pairs of single-light, wood casements. Two large, fixed sash picture windows and a picture window flaked by horizontal sliding sash are located on the west elevation. Although the windows appear to be replacements, the early-twentieth-century plan is relatively intact.

The south section is a two-story, three-bay-by-five-bay early-twentieth-century vernacular building. The asphalt shingle-clad, cross-gable roof has a brick chimney at each ridge. The walls are clad in vertical board siding and rest on a concrete block foundation. A side-gable, two-bay wide addition on the north addition was constructed after 1940. Full-width porches are attached to the first and second stories of the east elevation and are accessed by exterior staircases attached to the south elevation. The main entrance is located on the west (facade) elevation and consists of a solid door flanked by wide, full-height sidelights. The entrance is covered by a gable-front porch supported by square posts. Secondary entrances on the first and second stories of the east elevation, consists of sliding glass doors that access the porches. The basement level on the east elevation has two, fully-glazed doors. The windows consist of eight-over-eight, double-hung wood, replacement sash. Louvered metal vents are located in the gables on the facade and east elevation. The early-

**STATE OF CONNECTICUT**

**COMMISSION ON CULTURE & TOURISM  
STATE HISTORIC PRESERVATION OFFICE**

One Constitution Plaza, Second Floor, Hartford, CT 06103

**HISTORIC RESOURCE INVENTORY FORM**

For Buildings and Structures

**CONTINUATION SHEET**

Item Number: \_\_\_\_\_ Date: October 2011

PAL, Pawtucket, RI 02860

**47 Riverside Avenue, Westport, CT**

twentieth-century plan is still visible despite the two-story addition to the north elevation. Additional alterations include the mid-to-late-twentieth-century replacement materials like the windows and doors.

**Historical or Architectural importance:**

The building was constructed ca. 1890 and was used by Staples and Raymond Lumber and Building Materials in 1891, the earliest map depicting the buildings. However, only the north half of the extant building was constructed and were used as lumber sheds and a small office. By 1896, the property was occupied by Hill and Hubbell Lumber Yard, but by 1910, Westport Lumber Company was operating their lumber yard there. Westport Lumber Company constructed two buildings at the south end of the building between 1931 and 1940 and was located there through the 1960s. The 1970 directory lists ten businesses including a frame shop, a tea importers, and Bon Appétit restaurant. By 1980, ten more tenants had moved into the building. In 1991, fifteen businesses occupied the property including two publishers, a limousine service, and two importers. In 1996 the building was purchased by current owners Sumaran Limited Partnership. It presently contains a computer repair shop, a real estate office, a travel agency, and several offices, listed at 41-49 Riverside Avenue.

**Sources:**

Sanborn Fire Insurance Maps. 1891-1940; Westport Directory (W.D.). Loveland, CO: US West Marketing Resources, 1991; W.D. Chicago, IL: Johnson Publishing Co., 1985; W.D. Providence, RI: C. DeWitt White Co., 1917-1918; W.D. New Haven: The Price & Lee Co., 1923-1974; Westport Assessor's Online Database, 2012.

<i>FOR OFFICE USE ONLY</i>	
TOWN NO.:	SITE NO.:
UTM: 18/	/ / / / / / / /
QUAD:	
DISTRICT:	NR: Actual Potential



**STATE OF CONNECTICUT**

**COMMISSION ON CULTURE & TOURISM  
STATE HISTORIC PRESERVATION OFFICE**  
One Constitution Plaza, Second Floor, Hartford, CT 06103

**HISTORIC RESOURCE INVENTORY FORM**  
For Buildings and Structures

**CONTINUATION SHEET**

Item Number: \_\_\_\_\_ Date: October 2011  
PAL, Pawtucket, RI 02860

**47 Riverside Avenue, Westport, CT**

**PHOTOGRAPHS**

<i>FOR OFFICE USE ONLY</i>	
TOWN NO.:	SITE NO.:
UTM: 18/	/ / / / /
QUAD:	
DISTRICT:	NR: Actual Potential



View of the north and west elevations.



View of the west elevation.

**STATE OF CONNECTICUT**

**COMMISSION ON CULTURE & TOURISM  
STATE HISTORIC PRESERVATION OFFICE**

One Constitution Plaza, Second Floor, Hartford, CT 06103

**HISTORIC RESOURCE INVENTORY FORM**

For Buildings and Structures

**CONTINUATION SHEET**

Item Number: \_\_\_\_\_ Date: October 2011

PAL, Pawtucket, RI 02860

**47 Riverside Avenue, Westport, CT**

*FOR OFFICE USE ONLY*

TOWN NO.: \_\_\_\_\_ SITE NO.: \_\_\_\_\_

UTM: 18/\_\_\_\_/\_\_\_\_/\_\_\_\_/\_\_\_\_/\_\_\_\_

QUAD: \_\_\_\_\_

DISTRICT: \_\_\_\_\_ NR: Actual  
Potential



View of the west and south elevations.



View of the south and east elevations.

**STATE OF CONNECTICUT**

**COMMISSION ON CULTURE & TOURISM  
STATE HISTORIC PRESERVATION OFFICE**  
One Constitution Plaza, Second Floor, Hartford, CT 06103

**HISTORIC RESOURCE INVENTORY FORM**  
For Buildings and Structures

**CONTINUATION SHEET**

Item Number: \_\_\_\_\_ Date: October 2011  
PAL, Pawtucket, RI 02860

**47 Riverside Avenue, Westport, CT**

*FOR OFFICE USE ONLY*

TOWN NO.: \_\_\_\_\_ SITE NO.: \_\_\_\_\_  
UTM: 18/\_\_\_\_/\_\_\_\_/\_\_\_\_/\_\_\_\_/\_\_\_\_  
QUAD: \_\_\_\_\_  
DISTRICT: \_\_\_\_\_ NR: Actual  
Potential



View of the east elevations.



## HISTORIC RESOURCES INVENTORY - BUILDING AND STRUCTURES

Please send completed form to: Stacey Vairo, National Register and State Register Coordinator,  
Connecticut Commission on Culture & Tourism, One Constitution Plaza, 2nd Floor, Hartford, CT 06103

\* Note: Please attach any additional or expanded information on a separate sheet.

### GENERAL INFORMATION

Building Name (Common) \_\_\_\_\_  
 Building Name (Historic) Fairchild Store  
 Street Address or Location 1 Wilton Road  
 Town/City Westport Village \_\_\_\_\_ County Fairfield  
 Owner(s) 1 Wilton Rd. LLC  Public  Private

### PROPERTY INFORMATION

Present Use: Commercial  
 Historic Use: Commercial/Residential  
 Accessibility to public: Exterior visible from public road?  Yes  No  
 Interior accessible?  Yes  No If yes, explain \_\_\_\_\_  
 Style of building Federal with later Italianate details Date of Construction ca. 1830

Material(s) (Indicate use or location when appropriate):

- |  |   |                                      |  |  |
|--|---|--------------------------------------|--|--|
| <input checked="" type="checkbox"/> Clapboard  | <input type="checkbox"/> Asbestos Siding        | <input type="checkbox"/> Brick       | <input checked="" type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding  |
| <input checked="" type="checkbox"/> Fieldstone | <input type="checkbox"/> Board & Batten         | <input type="checkbox"/> Stucco      | <input type="checkbox"/> Cobblestone             | <input type="checkbox"/> Aluminum Siding |
| <input type="checkbox"/> Concrete (Type _____) | <input type="checkbox"/> Cut Stone (Type _____) | <input type="checkbox"/> Other _____ |  |  |

### Structural System

- Wood Frame  Post & Beam  Balloon  Load bearing masonry  Structural iron or steel  
 Other \_\_\_\_\_

### Roof (Type)

- Gable  Flat  Mansard  Monitor  Sawtooth  
 Gambrel  Shed  Hip  Round  Other \_\_\_\_\_

(Material)

- Wood Shingle  Roll Asphalt  Tin  Slate  Asphalt Shingle  
 Built up  Tile  Other \_\_\_\_\_

Number of Stories: 2 Approximate Dimensions \_\_\_\_\_

Structural Condition:  Excellent  Good  Fair  Deteriorated

Exterior Condition:  Excellent  Good  Fair  Deteriorated

Location Integrity:  On original site  Moved When? \_\_\_\_\_

Alterations?  Yes  No If yes, explain: \_\_\_\_\_

**FOR OFFICE USE:** Town # \_\_\_\_\_ Site # \_\_\_\_\_ UTM \_\_\_\_\_

District:  S  NR If NR, Specify:  Actual  Potential

**PROPERTY INFORMATION (CONT'D)**

**Related outbuildings or landscape features:**

- Barn       Shed       Garage       Carriage House       Shop       Garden
- Other landscape features or buildings: \_\_\_\_\_

**Surrounding Environment:**

- Open land     Woodland     Residential     Commercial     Industrial     Rural
- High building density       Scattered buildings visible from site

• Interrelationship of building and surroundings:

See Continuation Sheet

• Other notable features of building or site (*Interior and/or Exterior*)

See Continuation Sheet

Architect \_\_\_\_\_ Builder \_\_\_\_\_

• Historical or Architectural importance:

See Continuation Sheet

• Sources:

See Continuation Sheet

Photographer PAL \_\_\_\_\_ Date \_\_\_\_\_

View \_\_\_\_\_ Negative on File \_\_\_\_\_

Name \_\_\_\_\_ Date 12/13/2011

Organization PAL \_\_\_\_\_

Address 210 Lonsdale Avenue, Pawtucket, RI 02860

• Subsequent field evaluations:

**Threats to the building or site:**

- None known       Highways       Vandalism       Developers       Renewal       Private
- Deterioration       Zoning       Other \_\_\_\_\_       Explanation \_\_\_\_\_

**STATE OF CONNECTICUT**

**COMMISSION ON CULTURE & TOURISM  
STATE HISTORIC PRESERVATION OFFICE**

One Constitution Plaza, Second Floor, Hartford, CT 06103

**HISTORIC RESOURCE INVENTORY FORM**

For Buildings and Structures

**CONTINUATION SHEET**

Item Number: \_\_\_\_\_ Date: October 2011

PAL, Pawtucket, RI 02860

**1 Wilton Road, Westport, CT**

**Interrelationship of building and surroundings:**

The building is sited on a level lot at the northwest corner of Wilton Avenue and Post Road West. It is located close to the road and faces east. A tall fieldstone retaining wall edges the west and southwest boundaries of the property. A wood fence runs between the south end of the retaining wall to the southeast corner of the building. A paved parking lot located north of the house is accessed from Wilton Road.

**Other notable features of building or site (*Interior and/or Exterior*):**

The commercial building is two stories tall, two-bay-by-four-bay and constructed in the Federal style with later Italianate details. The asphalt shingle-clad, front-gable roof has a corbelled brick chimney at the ridge and a concrete block exterior chimney on the south elevation. The walls are clad in flush board on the first story of the east (facade) elevation and wood shingle on the west, north, and south elevations and rest on a fieldstone foundation. A wing was constructed between 1878 and 1891 on the east end of the south elevation. It has a side-gable roof, clapboard siding, and a fieldstone foundation. A lean-to on the west elevation is original to the plan or replaced an earlier one. A shed-roof awning extends across the entire facade and is supported by Italianate style brackets. The original primary entrance is located in the center of the main block. A pair of wood panel doors with louvers in the top half is in the center of the east (facade) elevation, but the primary entrance was relocated to the north end of the facade and consists of a wood panel door with simple wood trim. The entrance is accessible by a short staircase beneath the awning and has a wood arch spanning between two wood posts. Another prominent entrance is located in the center of the wing's facade and consists of a pair of wood panel doors with two-pane windows in the top half and simple wood trim. A secondary entrance is located off-center on the south elevation and covered by a shed roof with brackets. The symmetrical fenestration consists primarily of six-over-six, double-hung, mid-twentieth-century replacement windows in varying sizes with simple wood trim. The wing has two large, fifteen-light, fixed sash windows flanking the center entrance. A fanlight, most likely original to the design of the building, is located in the gable on the facade. Modern alterations include the replacement of the windows and exterior materials; however, the plan of the building has remained unchanged since the addition of the wing between 1878 and 1891.

**Historical or Architectural importance:**

The building was constructed ca. 1830 and appears on the 1855 map of the area. On Sanborn maps in the late-nineteenth century, the building is labeled as a grocery store. The address appears in the 1923 directory as the Westport Vulcanizing Shop, owned by Alfred Osborne. By 1937, the business name had changed to Westport Tire and Battery Service. In the early 1940s, the tire service was replaced by Crown Package Store, which changed its name to Corner Spirit Shop in the early 1950s. Corner Spirit Shop remained in the building through the early 1990s. The building is now owned by 1 Wilton Rd. LLC and contains The Needlework Shop on the ground floor and office/warehouse space on the upper floor.

**Sources:**

Beers, J.H. & Co. Atlas of the County of Fairfield. 1867; Clark, Richard. Fairfield County, Connecticut. 1855; HRI. Hartford: CT Historical Commission, 1986; Hopkins, G.M. Atlas of the County of Fairfield. 1879; Putney, Irving F. Free Hand Sketch of Road, Town of Westport, Prior to 1835. N.d.; Sanborn Fire Insurance Maps. 1891-1940; Westport Directory (W.D.). Loveland, CO: US West Marketing Resources, 1991; W.D. Chicago, IL: Johnson Publishing Co., 1985; W.D. Providence, RI: C. DeWitt White Co., 1917-1918; W.D. New Haven: The Price & Lee Co., 1923-1974; Westport Assessor's Online Database, 2011.

FOR OFFICE USE ONLY

TOWN NO.: \_\_\_\_\_ SITE NO.: \_\_\_\_\_

UTM: 18/\_\_\_\_/\_\_\_\_/\_\_\_\_/\_\_\_\_/\_\_\_\_

QUAD: \_\_\_\_\_

DISTRICT: \_\_\_\_\_ NR: Actual  
Potential

**STATE OF CONNECTICUT**

**COMMISSION ON CULTURE & TOURISM  
STATE HISTORIC PRESERVATION OFFICE**

One Constitution Plaza, Second Floor, Hartford, CT 06103

**HISTORIC RESOURCE INVENTORY FORM**

For Buildings and Structures

**CONTINUATION SHEET**

Item Number: \_\_\_\_\_ Date: October 2011

**PAL, Pawtucket, RI 02860**

**1 Wilton Road, Westport, CT**

**PHOTOGRAPHS**

*FOR OFFICE USE ONLY*

TOWN NO.: \_\_\_\_\_ SITE NO.: \_\_\_\_\_

UTM: 18/\_\_\_\_/\_\_\_\_/\_\_\_\_/\_\_\_\_/\_\_\_\_

QUAD: \_\_\_\_\_

DISTRICT: \_\_\_\_\_ NR: Actual  
Potential



View of the south and east elevations.



View of the south elevation.



## HISTORIC RESOURCES INVENTORY - BUILDING AND STRUCTURES

Please send completed form to: Stacey Vairo, National Register and State Register Coordinator,  
Connecticut Commission on Culture & Tourism, One Constitution Plaza, 2nd Floor, Hartford, CT 06103

\* Note: Please attach any additional or expanded information on a separate sheet.

### GENERAL INFORMATION

Building Name (Common) Vigilant Fire House  
 Building Name (Historic) Vigilant Hose Co. No. 3  
 Street Address or Location 6 Wilton Road  
 Town/City Westport Village \_\_\_\_\_ County Fairfield  
 Owner(s) Nathall 6W LLC  Public  Private

### PROPERTY INFORMATION

Present Use: Governmental  
 Historic Use: Governmental

Accessibility to public: Exterior visible from public road?  Yes  No  
 Interior accessible?  Yes  No If yes, explain \_\_\_\_\_  
 Style of building Colonial Revival Date of Construction 1931

Material(s) (Indicate use or location when appropriate):

- |  |   |   |                                       |  |
|--|---|---|---------------------------------------|--|
| <input type="checkbox"/> Clapboard             | <input type="checkbox"/> Asbestos Siding        | <input checked="" type="checkbox"/> Brick | <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding  |
| <input type="checkbox"/> Fieldstone            | <input type="checkbox"/> Board & Batten         | <input type="checkbox"/> Stucco           | <input type="checkbox"/> Cobblestone  | <input type="checkbox"/> Aluminum Siding |
| <input type="checkbox"/> Concrete (Type _____) | <input type="checkbox"/> Cut Stone (Type _____) | <input type="checkbox"/> Other _____      |                                       |  |

### Structural System

- Wood Frame  Post & Beam  Balloon  Load bearing masonry  Structural iron or steel  
 Other \_\_\_\_\_

### Roof (Type)

- Gable  Flat  Mansard  Monitor  Sawtooth  
 Gambrel  Shed  Hip  Round  Other \_\_\_\_\_

(Material)

- Wood Shingle  Roll Asphalt  Tin  Slate  Asphalt Shingle  
 Built up  Tile  Other \_\_\_\_\_

Number of Stories: 2 Approximate Dimensions \_\_\_\_\_

Structural Condition:  Excellent  Good  Fair  Deteriorated

Exterior Condition:  Excellent  Good  Fair  Deteriorated

Location Integrity:  On original site  Moved When? \_\_\_\_\_

Alterations?  Yes  No If yes, explain: \_\_\_\_\_

**FOR OFFICE USE:** Town # \_\_\_\_\_ Site # \_\_\_\_\_ UTM \_\_\_\_\_

District:  S  NR If NR, Specify:  Actual  Potential



**PROPERTY INFORMATION (CONT'D)**

**Related outbuildings or landscape features:**

- Barn       Shed       Garage       Carriage House       Shop       Garden
- Other landscape features or buildings: \_\_\_\_\_

**Surrounding Environment:**

- Open land     Woodland     Residential     Commercial     Industrial     Rural
- High building density       Scattered buildings visible from site

• Interrelationship of building and surroundings:

See Continuation Sheet

• Other notable features of building or site (*Interior and/or Exterior*)

See Continuation Sheet

Architect \_\_\_\_\_ Builder \_\_\_\_\_

• Historical or Architectural importance:

See Continuation Sheet

• Sources:

See Continuation Sheet

Photographer PAL \_\_\_\_\_ Date \_\_\_\_\_

View \_\_\_\_\_ Negative on File \_\_\_\_\_

Name \_\_\_\_\_ Date 12/13/2011

Organization PAL \_\_\_\_\_

Address 210 Lonsdale Avenue, Pawtucket, RI 02860

• Subsequent field evaluations:

**Threats to the building or site:**

- None known       Highways       Vandalism       Developers       Renewal       Private
- Deterioration       Zoning       Other \_\_\_\_\_       Explanation \_\_\_\_\_

**STATE OF CONNECTICUT**

**COMMISSION ON CULTURE & TOURISM  
STATE HISTORIC PRESERVATION OFFICE**  
One Constitution Plaza, Second Floor, Hartford, CT 06103

FOR OFFICE USE ONLY

TOWN NO.:            SITE NO.:  
UTM: 18/\_\_\_/\_\_\_/\_\_\_/\_\_\_/\_\_\_  
QUAD:  
DISTRICT:            NR: Actual  
                                        Potential

**HISTORIC RESOURCE INVENTORY FORM**  
For Buildings and Structures

**CONTINUATION SHEET**

Item Number: \_\_\_\_\_ Date: October 2011  
PAL, Pawtucket, RI 02860

**6 Wilton Road, Westport, CT**

**Interrelationship of building and surroundings:**

The building is sited on a level lot on the east side of Wilton Road. It is set close to the road and faces west. The building is surrounded on the south, east, and north by a paved parking lot. A flagstone sidewalk runs across the west elevation, and a cement sidewalk extends along the south side of the building. A wood fence wraps around a detached outbuilding on the north side of the building.

**Other notable features of building or site (*Interior and/or Exterior*):**

The building is a two-story, two-bays-by-four-bay, converted fire house constructed in the Colonial Revival style. The slate shingle-clad, front-gable roof has a molded cornice and rake with gable returns on the west (facade) elevation. A corbelled brick interior chimney is located near the ridge on the north slope. The walls are brick and have a brick beltcourse between the first and second stories on the south and north elevations. A recessed panel between the first and second stories on the facade contains a sign that reads "Vigilant Hose Co. No. 3, W.F.D." A five-story, three-bay brick hose tower that rises from the center of the east elevation was added to the plan ca. 1940. It has two-story rectangular recessed panels on the second and third stories of the south, east, and north elevations and two-story, round arch recessed panels on the fourth and fifth stories of all elevations. The original primary entrance consisted of one large garage bay. This entrance was replaced ca. 2002 with two segmental arch openings with splayed lintels infilled with plate glass windows. Secondary entrances include two glass doors with splayed lintels on the south elevation and a wood panel door with a splayed lintel on the east elevation of the tower. Windows consist of single and pairs of six-over-six, double-hung, mid-to-late-twentieth century replacement sash with limestone sills and splayed brick lintels. An entrance on the north elevation was filled with brick when the windows were replaced. The original plan of the building is relatively intact except for the tower addition.

**Historical or Architectural importance:**

The Vigilant Volunteer Hose Co. No. 3 was constructed in 1931 to replace an older wooden firehouse built ca. 1840. The firehouse operated through the early 1980s. Currently, the building is owned by Nathall 6W LLC and is being converted to retail space.

**Sources:**

Beers, J.H. & Co. Atlas of the County of Fairfield. 1867; Hopkins, G.M. Atlas of the County of Fairfield. 1879; Klein, Woody. Westport, Connecticut. Westport, CT: Greenwood Press, 2000; Sanborn Fire Insurance Maps. 1891-1940; Westport Directory (W.D.). Loveland, CO: US West Marketing Resources, 1991; W.D. Chicago, IL: Johnson Publishing Co., 1985; W.D. Providence, RI: C. DeWitt White Co., 1917-1918; W.D. New Haven: The Price & Lee Co., 1923-1974; Westport Assessor's Online Database, 2011; Westport Building Permit No. 61946.

**STATE OF CONNECTICUT**

**COMMISSION ON CULTURE & TOURISM  
STATE HISTORIC PRESERVATION OFFICE**

One Constitution Plaza, Second Floor, Hartford, CT 06103

**HISTORIC RESOURCE INVENTORY FORM**

For Buildings and Structures

**CONTINUATION SHEET**

Item Number: \_\_\_\_\_ Date: October 2011

**PAL, Pawtucket, RI 02860**

**6 Wilton Road, Westport, CT**

**PHOTOGRAPHS**

<i>FOR OFFICE USE ONLY</i>	
TOWN NO.:	SITE NO.:
UTM: 18/	/ / / / /
QUAD:	
DISTRICT:	NR: Actual Potential



View of the west and north elevations.



View of the north and east elevations.

**STATE OF CONNECTICUT**

**COMMISSION ON CULTURE & TOURISM  
STATE HISTORIC PRESERVATION OFFICE**

One Constitution Plaza, Second Floor, Hartford, CT 06103

**HISTORIC RESOURCE INVENTORY FORM**

For Buildings and Structures

**CONTINUATION SHEET**

Item Number: \_\_\_\_\_ Date: October 2011

**PAL, Pawtucket, RI 02860**

**6 Wilton Road, Westport, CT**

*FOR OFFICE USE ONLY*

TOWN NO.: \_\_\_\_\_ SITE NO.: \_\_\_\_\_

UTM: 18/\_\_\_\_/\_\_\_\_/\_\_\_\_/\_\_\_\_/\_\_\_\_

QUAD: \_\_\_\_\_

DISTRICT: \_\_\_\_\_ NR: Actual  
Potential



View of the east elevation.