Village District Overlay (VDO) Zone Westport Center §36;

The purpose of this Village District Overlay (VDO) is to protect the distinctive character, landscape, and historic structures and development pattern within this Village District while encouraging a mixed use, walkable district that is attractive to residents, employees, and visitors. New construction or substantial rehabilitation in the Village District should be compatible with the existing character of the district and reinforce both the existing development patterns and connections to the Saugatuck River. (See copy of Westport Regulations §36-2)

JOINT COMMITTEE

Village District Overlay (VDO) Zone / Westport Center REVIEW and RECOMMENDATION

1 2023 **1** 1 1023

D. 10 31 2023

HISTORIC DISTRICT

	Date: 10.31.2023 COMMISSION
Property Address: 75 Church Lane, Westport CT 06880	
Owner of Record: Episcopal Diocese of CT	Phone: 203 227 0827
Owner's Address: 75 Church Lane, Westport CT 06880	Email: klehn@chtwestport.org
Applicant's Name (if different): Deirdre O'Farrelly architect	Phone: 2038951960
Applicant's Address: 58 Wright Street, Westport CT 06880	Email: ofarrellyarchitects@gmail.com
Property Owner's Signature Legal E	epresentative's Signature (As authorized by owner)
If the applicant is unable to obtain property owner's signature, please submit a letter of authorization	on signed by the property owner with this application, as per 843-3.3

Required Review and Approvals for Properties Located in the VDO Zone:

- ☐ Certificate of Appropriateness (if property is located within a local historic district or designated a local historic property)
- ☐ Joint Committee Review and Recommendation of proposed design plans
- □ Compliance Alternative for Joint Committee Review (if applicant requests consideration of an alternative approach that satisfies the intent of the design principles but is not in compliance with design standards)
- ☐ Site Plan Approval by the Planning and Zoning Commission

Each application must be accompanied by:

- Completed application form.
- Narrative including description of the project, construction details, proposed materials and how the improvements are consistent with the style or how the improvements vary, a rationale of why the variation should be, approved under Sec 36-2.2.
- Historic Resources Inventory Form if applicable (Available from HDC Office).
- Site plan.
- Scaled building plans, including existing conditions plans and proposed plans.
- Photos showing the original historic building (if applicable), include photos of the buildings to either side of the proposed project and the view from across the street. A contrasting demonstration of the existing building in current streetscape and the proposed building within context of its surroundings
- Other materials deemed appropriate by applicant to enable the Joint Committee to evaluate the design.

One copy of the above required application and materials should be sent to the HDC office, Room 108 and digital copy emailed to the HDC Administrator, Donna Douglass, at ddouglass@westportct.gov. Hearings are typically held on the first Tuesday of each month at 7:00PM. The deadline for applications is 2 weeks prior to the next regularly scheduled meeting.

Joint Committee Recommendation to Planning and Zoning Commission:	
Signature:	Date:

CHRIST & HOLY TRINITY CHURCH, 75 Church Lane, Westport CT 068800

#65 Myrtle Ave. Rectory front porch and rear deck repairs



The front edge of the porch facing Myrtle ave., has dropped significantly as the supporting posts under each of the round columns have sunk sinking and or deteriorated over time and the supporting posts are sitting on stones without anchors. There are 8 to be replaced with concrete sonotube foundations., see attached section drawing.

The front stairs have sunk on the right handside and need to be rebuilt with new foundations.


The rear stair has collapsed altogether and has no foundation – note the railing post left sitting on a stone and needs to be rebuilt on a solid foundation.

The white round wood columns are in good condition but some of the bases need to be replaced.

The existing wood railing is non code-conforming – it is 8" too low and dangerous, needs repair, adding top rail and raising the bottom rail to 4" above the deck will make the railing height 36" above the porch floor and strengthen the whole railing.

The framing below the deck is good but needds to have joist hangars installed to stiffen the structure.

The new 6x6 PT posts need to be anchored to the conc. foundations to prevent uplift and to the load-bearing wood columns holding up the roof above.





Existing Corner post



Rear stair has collapsed.



Posts sitting on stone foundations



Deterioration of load bearing base of corner post.



Front steps are collapsing on the right side & require foundations under the existing circular columns.



Framing under the deck


CHRIST & HOLY TRINITY CHURCH, WESTPORT

65 Myrtle Ave. Associate Rectory rear deck repairs

The deck framing is in good condition and has sonotube foundations supporting the posts. Timbertech, light grey, boarding is suggested to replace the deteriorated decking and stairs, additional joists will need to be added as they are spaced at 16" and need to be at 12" for Timbertech.

The upper landing and stair to the deck at the Mudroom door will be replaced with timbertech and the two stes of steps to grade will be replaced with timebertech.


The existing railing and posts are to be protected and maintained.





Deteriorated decking is splintered.

Concrete sonotube foundations, railing & posts to remain.



HISTORIC RESOURCES INVENTORY—BUILDINGS AND STRUCTURES

State Historic Preservation Office, Department of Economic and Community Development 450 Columbus Boulevard, Suite 5
Hartford, CT 06103

GENERAL INFORM	MATION			
Building Name (Common)	.)			
Building Name (Historic)				
Street Address or Location	n75 C		ormerly 65 Myrtle Street)	F : 6 11
Town/City: Westport		Village:	Co	unty: Fairfield
Owner(s): Christ & Holy	Trinity Church		Publ	ic Private
PROPERTY INFOR	RMATION			
Present Use Resid	ence			
Historic Use Reside	ence			
Accessibility to Public: E	Exterior visible fro	om public road?	Yes No	
Interior accessible? Y	es	No If yes, expla	ain	
Style of building: Colonia	al Revival		Date of Construc	tion c. 1910
Materials (Indicate use or	r location when ap	propriate):		
Clapboard Asi	sbestos Siding	Brick	Wood Shingle	Asphalt Siding
Fieldstone Bo	oard & Batten	Stucco	Cobblestone	Vinyl Siding
Concrete (Type)		Cut Ston	ne (Type):	Other:
Structural System				
Wood Frame	Post & Beam	⊠ Balloon	Load-bearing Masonry	Structural iron or steel
Other				
Roof (<i>Type</i>)				
⊠ Gable □	Flat	Mansard	Monitor	Sawtooth
Gambrel	Shed	Hip	Round	Other —
(Material)				
Wood Shingle] Roll Asphalt	Tin	Slate	Asphalt Shingle
Built up	Tile	Other		
	-			
Number of Stories: 2	Approx	imate Dimensions	30 x 30; 20 x 11;	plus porch and rear deck
Structural Condition:	☐ Exc	cellent	Good Fair	Deteriorated
Exterior Condition:	□ I	Excellent	Good Fair	Deteriorated
Alterations?	Yes No	If yes, expla	ain: Some window sash rep	laced; rear deck; skylight
FOR OFFICE USE	Town #	Site	UTM	
☐ District		NR, Specify:	Actual	Potential

PROPERTY I	NFORMATION	(CONT'D)				
Related outbuildi	ings or landscape fe	atures:				
Barn	Shed	☐ Garage	Carriage House	Shop	Garden	
Other landsca	pe features or buildin	gs:				
Surrounding Env	ironment:					
Open land	Woodland	Residentia	l 🛛 Commercial	☐ Industrial	Rural	
—			ouildings visible from sit		_	
• Interrelationship	o of building and sur		C			
elevated above to buildings, conne	he campus parking	lot to the west. ue and the parki	Mackenzie House staing lot below. The gar	nds to the sout	Myrtle Avenue, and the site is h. A drive runs between the two agon house) is located down a	
• Other notable fe	atures of building o	r site (Interior a	nd/or Exterior)			
gables oriented on columns with frames the entry its original six-p joined by a narr appears to the ri chimney on the	to the north and sound Doric capitals from the property, which is offset to panel door and a decow transom panel. In a ght. Among other in north side. On the whits peak. An enclose	on the cast elements the house, we the left (south) corative surrour A picture windomotable features west elevation,	evation serves as the forapping around its not side of the façade. The dincorporating oversow incorporating similare the houses deep ca central triangular ga	açade, and a or orthwest corner his architectura sized sidelights lar side panels overhanging roo ble intersects v	with a square plan, peaked roof ne-story hip-roofed porch mount. The southernmost porch bay I feature is notable for preserving with double-X crossbar glazing and cross-bar glazing across its of eaves and its cobblestone with the roof, receiving a brick ear, accessed by a small entry	ed g
Architect			Builder			
• Historical or Arc	chitectural Importa	ice:				
bar window glaz garage, built con Holy Trinity Chr Prior to its owne	ing on its east faça temporaneously wi urch campus around	de and in the co th the house, is d the 1960s, and this address w	bblestone masonry us a significant outbuild I has served as curate as the residence of the	ed to fabricate ing. The house s and rector's	features of the style in the cross its chimney and foundation. The was absorbed into the Christ & residence, refectory and offices. dward C. Birge (1920s-30s);	e
• Sources:						
Town of Westp Sanborn Fire In HRI, PAL, 201						
Photographer: Ra	chel Carley Date:					
View: From the ear	st					
Name: Rachel Car	ley Date	: /22				
10 Ca	ng or site:	↑ Vandalism				
Deterioration	☐ Highways ☐ Zoning	☐ Other		1		

PROPERTY INFORMATION (CONT'D)



65 Myrtle Avenue looking northwest



65 Myrtle Avenue looking north



65 Myrtle Avenue, garage (wagon house), looking east

STATE OF CONNECTICUT

CONNECTICUT HISTORICAL COMMISSION 59 South Prospect Street, Hartford, CT 06106

HISTORIC RESOURCES INVENTORY FORM

For Buildings and Structures

CONTINUATION SHEET

Item number: _____

PAL, Pawtucket, RI 02860

June 2000

Address:

65 Myrtle Avenue 75 Church Lane

Name:

House

NR District:

Local District:

Neg No.:

23:12

HRS ID No .:

0574

